





report date: 2024-03-30

General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V
Colour	Grey
Year of manufacture	2007
Top speed	96 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	105 Nm at 3.500 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	163 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-28

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-23
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	11
Total items failed	2

MOT #18	2024-01-05 12:30
MOT test number	398182739194
Result	✓ Passed
Next expiry date	2025-01-23
Minor Offside Outer Drive shaft joint constant velocity boot severely deterio (g) (i))	rated Pinhole in gaiter (6.1.7

MOT #17	2024-01-03 09:27
MOT test number	394474072073
Result	× Failed
MAJOR Nearside Rear Service brake excessively binding (1.2.1 (f))	
DANGEROUS Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))	
MAJOR Offside Rear Service brake lagging in operation (1.2.1 (d))	
Minor (g) (i)) Offside Outer Drive shaft joint constant velocity boot severely deteriorated P	inhole in gaiter (6.1.7

MOT #16	2023-01-10 11:34
MOT test number	662174569932
Result	✓ Passed
Minor Offside Registration plate lamp inoperative in the case of multip	le lamps or light sources (4.7.1 (b)

CarCheck.co.uk page 3/13



RX07LEU

report date: 2024-03-30

MOT test number 821104002084

Result ✓ Passed

MOT #14 2021-05-22 08:19

MOT test number 373207834520

Result ✓ Passed

MOT #13 2020-06-22 11:14

MOT test number 607468279991

Result \(\sqrt{Passed} \)

MOT #12 2019-05-09 10:19

MOT test number 156696865404

MOT #11 2019-05-09 08:09

MOT test number 196011223247

Result X Failed

MAJOR Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10 2018-05-02 09:42

MOT test number 252766228763

Result \(\sqrt{Passed} \)

Advice Travel on parking brake lever

MOT #9 2017-05-04 08:23

MOT test number 508625359063

Result

Passed

CarCheck.co.uk page 4/13



RX07LEU

report date: 2024-03-30

MOT #8		2016-04-30 10:07
MOT test	number	897924361159
Result		✓ Passed
Advice	Centre Hand brake requires adjustment	
Advice Nearside Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt oil weep from cv (2.5.C.1a)		

centre riana brake requires adjustiment	
Advice Nearside Inner Front constant velocity joint g	aiter damaged, but preventing the ingress of dirt oil
weep from cv (2.5.C.1a)	
MOT #7	2015-05-16 11:51
MOT test number	639536135140
Result	✓ Passed
MOT #6	2014-05-20 14:40
MOT test number	245780544429
Result	✓ Passed
MOT #5	2013-05-07 12:54
MOT test number	299457423489
Result	✓ Passed
MOT #4	2012-05-09 10:46
MOT test number	545450232110
Result	✓ Passed
MOT #3	2011-05-11 10:45
MOT to at assemble as	246251421402

MOT #3	2011-05-11 10:45
MOT test number	246351431492
Result	✓ Passed

CarCheck.co.uk page 5/13



RX07LEU

report date: 2024-03-30

MOT test number

Result

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification

Centre Exhaust system not adequately supported (7.1.1)

MOT #1	2010-05-13 16:12
MOT test number	143473930129
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e union mestery	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in	

	More info >
Plate changes See in this check if this RENAULT had different number plates.	
Number of plates	,
Correct registration	NK NA
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-21
Last registration	2024-01-05
Complete history	See info



Registration #1	2007-05-21	12 mi
Registration #2	2010-05-13	11.806 mi
Registration #3	2011-05-11	14.465 mi
Registration #4	2012-05-09	16.492 mi
Registration #5	2013-05-07	18.226 mi
Registration #6	2014-05-20	19.638 mi
Registration #7	2015-05-16	20.877 mi
Registration #8	2016-04-30	24.841 mi
Registration #9	2017-05-04	28.632 mi
Registration #10	2018-05-02	33.485 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		0.77 44
Registration #19		0.0746

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

F041742