



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	White
Year of manufacture	2012
Top speed	117 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	170 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-09-14
Pictures	30
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-30
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	28
Total items failed	1

MOT #112024-03-26 14:57

MOT test number765245150685

Result✓ Passed

Next expiry date2025-03-30

- AdviceRear Coil spring corroded nearside and offside (5.3.1 (b) (i))
- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceRear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceBrake pipe corroded, covered in grease or other material main run to the side of the fuel tank (1.1.11 (c))
- AdviceNearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2024-03-23 10:35

**MOT test number**

198071058302

**Result****✗ Failed**

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material main run to the side of the fuel tank (1.1.11 (c))

**MOT #9**

2023-03-17 09:29

**MOT test number**

717898969570

**Result****✓ Passed**

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Shock absorbers has light misting of oil Both (5.3.2 (b))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8**

2022-03-31 09:18

**MOT test number**

381345374017

**Result****✓ Passed**

**MOT #7** 2021-05-10 07:41**MOT test number** 306100853277**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Rear Exhaust mounting defective middle to rear exhaust joint heavily corroded (6.1.2 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Oil leak, but not excessive around sump pan area (8.4.1 (a) (i))

**MOT #6** 2020-06-03 10:25**MOT test number** 673059523943**Result** ✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5** 2019-06-01 08:53**MOT test number** 775149547166**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #4** 2018-06-11 13:44**MOT test number** 777779681447**Result** ✓ Passed



MOT #3	2017-08-14 08:33
MOT test number	523835231691
Result	✓ Passed
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)

MOT #2	2016-08-20 08:53
MOT test number	176779061093
Result	✓ Passed

MOT #1	2015-08-18 16:07
MOT test number	425104950507
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
30 March 2025

Tax status		Valid until 1 September
Days left		124
MOT expiry date		30 March 2025
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YX62PVJ
Plate since	2019-03-29
Current registration	 YX62PVJ
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-06
Last registration	2024-03-26
Complete history	<a href="#">See info</a>



Registration #1	2012-09-06	19 mi
Registration #2	2015-08-18	23.823 mi
Registration #3	2016-08-20	32.541 mi
Registration #4	2017-08-14	40.549 mi
Registration #5	2018-06-11	46.874 mi
Registration #6	2019-06-01	56.993 mi
Registration #7	2020-06-03	65.128 mi
Registration #8	2021-06-03	75.277 mi
Registration #9	2022-06-03	85.426 mi
Registration #10	2023-06-03	95.575 mi
Registration #11	2024-03-26	105.724 mi
Registration #12	2024-03-26	115.873 mi
Registration #13	2024-03-26	126.022 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	172361K