





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SPORT
Colour	Black
Year of manufacture	2007
Top speed	128 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2023-01-03

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-09-08

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-09-05
MOT pass rate	100 %
MOT passed	13
Failed MOT tests	0
Total advice items	18
Total items failed	0

MOT #13		2023-09-06 06:37
MOT test	number	697438381522
Result		✓ Passed
Next expi	ry date	2024-09-05
Advice	Central Front engine oil near exhaust	
Advice	Rear rear brakes require stripping and cleaning	
Advice	Central Rear high level brake light dim	
Advice	Offside Front Outer sills soft	
Advice	Nearside Rear cuts to side wall	
Advice	Nearside Front Lower sills soft	

MOT #12	2022-08-04 15:15
MOT test number	397854273976
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))	

MOT #11		2021-08-03 15:36
MOT test	number	673462518871
Result		✓ Passed
Advice	Offside Rear Anti-roll bar linkage modified but not seriously weakened (5.3.3 (c) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10 2020-07-04 14:16

MOT test number 307707734233

Result \(\sqrt{Passed} \)

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #9 2019-03-30 17:54

MOT test number 549122922899

Result \(\sqrt{Passed} \)

MOT #8 2018-04-21 16:06

MOT test number 920520573760

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2017-04-24 16:39

MOT test number 759618603047

Result ✓ Passed

MOT #6 2016-04-13 11:04

MOT test number 993428404072

Advice Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice All tyres slight perishing

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress

of dirt (2.5.C.1a)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5 2015-04-08 11:37

MOT test number 145988695401

Result ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #4 2013-11-15 12:17

MOT test number 167589813345

MOT #3 2012-11-07 12:48

MOT test number 795202212394

Result ✓ Passed

MOT #2 2011-11-16 12:42

MOT test number 397060221392

Result

Passed

MOT #1 2010-11-24 15:05

MOT test number 713328820316

Result
✓ Passed

Notice 2x front tyres signs off uneven wear on inner edges

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	5 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK ZIN
Plate since	
Current registration	NK.
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-12-04
Last registration	2023-09-06
Complete history	See info



Registration #1	2007-12-04	10 mi
Registration #2	2010-11-24	29.009 mi
Registration #3	2011-11-16	36.209 mi
Registration #4	2012-11-07	44.220 mi
Registration #5	2013-11-15	54.825 mi
Registration #6	2015-04-08	63.422 mi
Registration #7	2016-04-13	69.502 mi
Registration #8	2017-04-24	73.848 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		11.777 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		10.377 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1671 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
CarChaeleeaule	naga 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	BKP 215735