





report date: 2024-03-30

General information

| Make | MINI |
|---------------------|--|
| Model | COOPER S ELECTRIC LEVEL 2 COOPER S LEVEL 2 |
| Colour | Green |
| Year of manufacture | 2021 |
| Top speed | 93 mph |
| Gearbox | -automatic |

Engine & fuel consumption

| Power | 181 BHP |
|----------------------|---------------------|
| Max. torque | 270 Nm at 1.000 rpm |
| Fuel type | Electricity |
| Consumption combined | 1.0 mpg |



CarCheck.co.uk page 1/10



Internet history

Entry 3

Date 2022-07-26


Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

| Date | 2021-12-20 |
|------|------------|
| | |

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-12-20 | |
|---------------|-------------|--|
| Pictures | 0 | |
| Listing price | View report | |

source: heycar.co.uk

CarCheck.co.uk page 2/10



MOT history

| MOT expiry date | 2025-03-24 |
|--------------------|------------|
| MOT pass rate | 50 % |
| MOT passed | 1 |
| Failed MOT tests | 1 |
| Total advice items | 2 |
| Total items failed | 3 |

| MOT #2 | 2024-03-21 17:05 |
|------------------|------------------|
| MOT test number | 740047723646 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-24 |

| MOT #1 | | 2024-03-20 15:09 |
|---|--|-------------------|
| MOT test number | | 698683524173 |
| Result | | X Failed |
| Advice Vehicles interna | headlight adjuster altered to recheck lights | |
| Advice Tyre worn close | to legal limit/worn on edge Tyre heavily worn on inner | edge (5.2.3 (e)) |
| Pass with rectification | Offside Headlamp aim too high and too far to the rig | ht. (4.1.2 (a)) |
| Fail Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) | | |
| Pass with rectification | Nearside Headlamp aim too high and too far to the ri | ight. (4.1.2 (a)) |

CarCheck.co.uk page 3/10



Tax & MOT check



Days left 93

MOT expiry date 24 March 2025

Full MOT history See MOT history

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



| Owner | history |
|--------|---------|
| OWITEL | HISLULY |

| For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is | | e? |
|--|-----------|----|
| | | |
| THE STATE OF THE S | | |
| *************************************** | | |
| *************************************** | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this MINI had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 7/10



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2021-03-25 |
| Last registration | 2024-03-21 |
| Complete history | See info |



| Registration #1 | 2021-03-25 | 21 mi |
|-----------------|------------|-----------|
| Registration #2 | | D.777 es |
| Registration #3 | | 9.77 sc |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 11.777 es |
| Posistration #6 | | |

Registration #6

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 60569 | |

Dimensions & weight

| Width | 1727 mm |
|--------|---------|
| Height | 1432 mm |
| Length | 3850 mm |

Additional information

| Number of axles | 2 |
|-----------------|---------|
| Engine number | UNKNOWN |

CarCheck.co.uk page 10/10