





report date: 2024-03-28

## General information

Make	BMW
Model	X1 SDRIVE20I XLINE
Colour	White
Year of manufacture	2018
Top speed	140 mph
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	189 BHP
Max. torque	281 Nm at 1.350 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	37.7 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history

E	n	t	r۱	,	2
E	n	τ	r٧	•	Z

Date	2021-12-16
Pictures	0
Listing price	View report

#### source: heycar.co.uk

#### Entry 1

, _	
Date	2021-12-15
Pictures	1
Listing price	<u>View report</u>



source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

MOT expiry date	2025-01-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5		2023-12-29 16:44
MOT test	number	576758400404
Result		✓ Passed
Next expi	ry date	2025-01-24
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



Result

DK680BD

report date: 2024-03-28

✓ Passed

**MOT #4** 2023-12-29 15:46 861486181300 **MOT** test number Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Side repeater not working (4.4.1 (a) (ii)) Fail

MOT #3

MOT test number

939791386252

Result

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2	2022-01-25 16:09
MOT test number	390292856471
Result	<b>✓</b> Passed
MOT #1	2021-11-09 11:58
MOT test number	485899492194

CarCheck.co.uk page 4/11



DK680BD report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	24 January 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner	history
OWITE	HISLULY

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report		ve?
***************************************		
***************************************		
	More info	
	More into	
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		, ,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-11-29
Last registration	2023-12-29
Complete history	See info



Registration #1	2018-11-29	10 mi
Registration #2	2021-11-09	10.397 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.117 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1821 mm
Height	1598 mm
Length	4439 mm
Wheel base	2670 mm
Kerb weight	1480 kg
Max. allowed weight	2065 kg

# Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

**Engine number** F467H975