



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 COUPE CABRIOLET S
Colour	Blue
Year of manufacture	2002
Top speed	120 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.5 mpg
Consumption combined	40.3 mpg
CO2 emission	166 g/km
CO2 label	H






## Internet history

### Entry 5

Date 2021-10-06

Pictures 5

Listing price [View report](#)






source: [autotrader.co.uk](#)

### Entry 4

Date 2021-09-27

Pictures 5

Listing price [View report](#)






source: [autotrader.co.uk](#)

### Entry 3

Date 2021-09-27

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](#)

### Entry 2

Date 2021-09-12





CarCheck.co.uk

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date




2021-09-04

Pictures

5

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-14
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	57
Total items failed	27

MOT #27	2022-11-15 13:48
---------	------------------

MOT test number	833394048295
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-11-14
------------------	------------

- AdviceEngine warning light on
- AdviceNearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Registration lamp cover missing.
- AdviceOil leak, but not excessive (8.4.1 (a) (i))
- AdviceCentral Stop lamp unit some LED lights not working
- AdviceAdvise exhaust tail pipe close to rear bumper.
- AdviceOffside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- AdviceNearside Front Fog lamp missing

**MOT #26**

2022-11-15 11:57

**MOT test number**

793043712510

**Result****✗ Failed****Fail**

Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail**

Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))

**Advice**

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Nearside Registration lamp cover missing.

**Advice**

Central Stop lamp unit some LED lights not working

**Advice**

Engine warning light on

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Advice**

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

Advise exhaust tail pipe close to rear bumper.

**Advice**

Nearside Front Fog lamp missing

**MOT #25**

2021-08-09 14:28

**MOT test number**

200300470493

**Result****✓ Passed****MOT #24**

2021-08-09 14:28

**MOT test number**

110195195808

**Result****✗ Failed****Pass with rectification**

Offside Headlamp aim too low (4.1.2 (a))

**Pass with rectification**

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Pass with rectification**

Nearside Headlamp aim too low (4.1.2 (a))

**Pass with rectification**

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



<b>MOT #23</b>	2020-08-11 16:17
<b>MOT test number</b>	910622929192
<b>Result</b>	✓ Passed
<b>Advice</b>	ENGINE MIL LAMP ON

<b>MOT #22</b>	2020-08-11 14:51
<b>MOT test number</b>	884009891852
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))
<b>Fail</b>	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
<b>Pass with rectification</b>	Nearside Headlamp aim too high (4.1.2 (a))
<b>Advice</b>	ENGINE MIL LAMP ON

<b>MOT #21</b>	2019-08-09 14:20
<b>MOT test number</b>	578238309423
<b>Result</b>	✓ Passed

<b>MOT #20</b>	2019-08-09 14:20
<b>MOT test number</b>	609012662581
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Front Direction indicator incorrect colour (4.4.3 (a))

<b>MOT #19</b>	2018-08-14 15:46
<b>MOT test number</b>	903331110946
<b>Result</b>	✓ Passed

**MOT #18** 2018-08-14 14:06**MOT test number** 364791215048**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Windscreen washer not working (3.5 (a))**MOT #17** 2017-08-03 13:50**MOT test number** 653758471682**Result** ✓ Passed**MOT #16** 2016-07-28 11:00**MOT test number** 273298271531**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #15** 2015-08-07 11:59**MOT test number** 118200652160**Result** ✓ Passed**MOT #14** 2015-08-07 11:59**MOT test number** 144889846042**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #13** 2014-08-06 12:48**MOT test number** 499498214215**Result** ✓ Passed**MOT #12** 2014-07-28 11:31**MOT test number** 236729404209**Result** ✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #11** 2013-07-25 16:48**MOT test number** 616276003283**Result** ✓ Passed

- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nearside front foglight lense cracked



**MOT #10**

2013-07-23 17:34

**MOT test number**

388464803442

**Result**

✗ Failed

**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Nearside rear tyre out of shape**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Nearside front foglight lense cracked**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #9**

2012-08-02 17:28

**MOT test number**

575775512213

**Result**

✓ Passed

**Notice** 2x winter tyres fitted**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Service light on**Notice** Wipers deteriorated**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #8** 2012-08-02 16:30**MOT test number** 577625512271**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Notice** 3x winter tyres fitted**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Service light on**Notice** Wipers deteriorated**MOT #7** 2011-07-27 11:42**MOT test number** 366698101246**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-07-23 11:08**MOT test number** 966954801271**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Front Lower Suspension arm has excessive play in a pin/bush (2.4.G.2)**Notice** Nail in nearside rear tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #5** 2010-07-24 12:25**MOT test number** 970125600266**Result** ✓ Passed**Advice** Nearside Front Lower Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2009-05-20 12:48**MOT test number** 790770749187**Result** ✓ Passed**MOT #3** 2008-05-22 15:36**MOT test number** 902113548126**Result** ✓ Passed



MOT #2	2007-04-26 11:31
MOT test number	462816317198
Result	✓ Passed
Notice	Front discs rusty
Notice	Both rear tyres perished
Notice	Rear silencer weak

MOT #1	2006-05-22 11:57
MOT test number	632682546143
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
28 January 2024

X

MOT

Expired:  
14 November 2023

Tax status	Expired at 28 January 2024
Days left	92 days too late
MOT expiry date	14 November 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	33
First mileage registration	2002-05-17
Last registration	2022-11-15
Complete history	<a href="#">See info</a>



Registration #1	2002-05-17	8 mi
Registration #2	2006-05-22	12.151 mi
Registration #3	2007-04-26	16.479 mi
Registration #4	2008-05-22	25.042 mi
Registration #5	2009-05-20	31.062 mi
Registration #6	2010-07-24	39.704 mi
Registration #7	2011-07-23	55.194 mi
Registration #8	2011-07-27	55.245 mi
Registration #9	2012-08-02	76.633 mi
Registration #10	2012-08-02	76.635 mi
Registration #11	2013-07-23	86.846 mi
Registration #12	2013-07-25	86.975 mi
Registration #13	2014-07-28	90.588 mi
Registration #14	2014-08-06	90.588 mi
Registration #15	2015-08-07	94.843 mi
Registration #16	2015-08-07	94.843 mi
Registration #17	2016-07-28	98.806 mi
Registration #18	2016-08-01	98.806 mi
Registration #19	2016-08-01	98.806 mi
Registration #20	2016-08-01	98.806 mi
Registration #21	2016-08-01	98.806 mi
Registration #22	2016-08-01	98.806 mi
Registration #23	2016-08-01	98.806 mi
Registration #24	2016-08-01	98.806 mi
Registration #25	2016-08-01	98.806 mi
Registration #26	2016-08-01	98.806 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442
Registration #33	2025-25-25	25,252,442

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1140 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Engine number	FX2F1581187