





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|----------------------------|
| Model | 140 CRDI ACTIVE BLUE DRIVE |
| Colour | Black |
| Year of manufacture | 2014 |
| Top speed | 118 mph |
| 0 - 60 mph | 12.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 114 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 2.750 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 113 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



Internet history


Entry 2

| Date | 2021-07-26 | |
|---------------|-------------|--|
| Pictures | 0 | |
| Listing price | View report | |

source: cargurus.co.uk

Entry 1

| Date | 2021-07-25 | |
|---------------|--------------------|--|
| Pictures | 23 | |
| Listing price | <u>View report</u> | |









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-07-29 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 13 |
| Total items failed | 0 |

| MOT #11 | 2023-07-10 09:40 |
|--|------------------|
| MOT test number | 775224030099 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-29 |
| Advice Items removed from driver's view prior to test | |
| Advice Offside Front Service brake binding but not excessively (1.2.1 (f)) | |

| MOT #10 | 2022-07-29 09:02 |
|--|------------------|
| MOT test number | 706837041237 |
| Result | ✓ Passed |
| Advice Engine covers & under trays fitted, unable to check some components | |

| MOT #9 | | 2022-07-28 09:07 |
|----------|---|-----------------------|
| MOT test | number | 814192966107 |
| Result | | 🗙 Failed |
| MAJOR | Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i)) | |
| MAJOR | Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Advice | Engine covers & under trays fitted, unable to check some components | |
| DANGER | OUS Offside Rear Brake pad(s) less than 1.5 mm thick signs of brake getting | hot (1.1.13 (a) (ii)) |

CarCheck.co.uk page 3/12



EN14TWK

report date: 2024-03-28

MOT test number 677683663912

Result
✓ Passed

MOT #7 2021-01-29 10:32

MOT test number 797428056479

Result ✓ Passed

MOT #6 2020-02-25 10:15

MOT test number 891895506968

Result
✓ Passed

MOT #5 2020-02-19 09:30

MOT test number 690673749591

Result X Failed

MAJOR Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))

DANGEROUS Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #4 2019-07-22 14:06

MOT test number 165806820422

MOT #3 2018-07-23 13:55

MOT test number 979672589848

Result ✓ Passed

CarCheck.co.uk page 4/12



MOT #2 2018-07-23 12:33

MOT test number 537090633491

Result X Failed

DANGEROUS Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

DANGEROUS Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

MOT #1 2017-06-30 08:27

MOT test number 932641066418

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 29 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



EN14TWK

report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| e when mistery | | |
|--|-----------|-------------|
| For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | | DAI |
| | | |
| | | |
| | | |
| | | |
| ******** | | |
| *************************************** | | |
| *************************************** | | |
| | | |
| | More info | > |
| Plate changes | | |
| See in this check if this HYUNDAI had different number plates. | | |
| Number of plates | | , |
| Current registration | UK UK | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 10/12



EN14TWK

report date: 2024-03-28

Mileage check

Registration #14

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2014-07-22 |
| Last registration | 2023-07-10 |
| Complete history | See info |



| Registration #1 | 2014-07-22 | 20 mi |
|------------------|------------|-----------|
| Registration #2 | 2017-06-30 | 41.117 mi |
| Registration #3 | 2018-07-23 | 58.758 mi |
| Registration #4 | 2018-07-23 | 58.759 mi |
| Registration #5 | 2019-07-22 | 72.506 mi |
| Registration #6 | 2020-02-19 | 76.776 mi |
| Registration #7 | 2020-02-25 | 76.874 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.777 es |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 11.777 mi |
| | | |

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 86% |
| Pedestrian | 43% |
| Safety systems | 86% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1815 mm |
|---------------------|---------|
| Height | 1470 mm |
| Length | 4770 mm |
| Wheel base | 2770 mm |
| Kerb weight | 1638 kg |
| Max. allowed weight | 2120 kg |

Additional information

| Fuel tank capacity | 70 I | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2

Engine number D4FDDU320153