




report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	White
Year of manufacture	2012
Top speed	97 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-28
Pictures	5
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2021-11-18
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	6
Total items failed	11

MOT #11	2020-11-19 11:30
MOT test number	907949767154
Result	✓ Passed
Next expiry date	2021-11-18
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #10	2020-11-18 13:36
MOT test number	401978481972
Result	✗ Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Offside Rear Suspension component pin or bush excessively worn front bush (5.3.4 (a) (i))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

MOT #9	2019-11-14 11:36
MOT test number	900430956888
Result	✓ Passed



MOT #8	2019-11-07 09:07
MOT test number	212893941432
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too high Adjusted (4.1.2 (a))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush bonding (5.3.4 (a) (i))
Pass with rectification	Offside Front Headlamp aim too high Adjusted (4.1.2 (a))

MOT #7	2018-10-24 15:43
MOT test number	470212073077
Result	✓ Passed

MOT #6	2018-07-07 09:47
MOT test number	609755996042
Result	✓ Passed

MOT #5	2018-07-04 06:52
MOT test number	468639508153
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #4	2017-06-27 08:01
MOT test number	438985951880
Result	✓ Passed



MOT #3	2016-07-06 10:26
MOT test number	219910413246
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2	2016-07-06 10:26
MOT test number	297765840345
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #1	2015-07-07 13:57
MOT test number	248538585152
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner 1	Start	End
Owner 2	Start	End
Owner 3	Start	End
Owner 4	Start	End
Owner 5	Start	End
Owner 6	Start	End

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	VAUXH
Plate since	2019-03-29
Current registration	VAUXH
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-30
Last registration	2020-11-19
Complete history	See info



Registration #1	2012-06-30	21 mi
Registration #2	2015-07-07	24.598 mi
Registration #3	2016-07-06	36.884 mi
Registration #4	2016-07-06	36.884 mi
Registration #5	2017-06-27	47.941 mi
Registration #6	2018-07-04	60.403 mi
Registration #7	2018-07-07	60.426 mi
Registration #8	2019-06-27	60.377 mi
Registration #9	2019-06-27	60.377 mi
Registration #10	2019-06-27	60.377 mi
Registration #11	2019-06-27	60.377 mi
Registration #12	2019-06-27	60.377 mi
Registration #13	2019-06-27	60.377 mi

[More info >](#)



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	4682811