





report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER EVOQUE R-DYN D 4X2 S
Colour	Black
Year of manufacture	2020
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	44.8 mpg
CO2 emission	143 g/km
CO2 label	F



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-08

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



BU20PCX report date: 2024-03-28

MOT history

MOT expiry date	2025-02-28
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #3	2024-02-26 10:21
MOT test number	733001073233
Result	✓ Passed
Next expiry date	2025-02-28
Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Low tyre pressure light on	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #2	2023-02-28 15:56
MOT test	number 493885684777
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
Advice	Bonnet release handle damaged
Advice	Nearside Rear Tyre slightly damaged small cut not deep enough to reach ply or cord (5.2.3 (d) (ii))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2023-02-28 09:43

MOT test number 717295029169

Result X Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm and tread heavily damaged (235/65/17) (5.2.3 (e))

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Front Tyre tread depth below requirements of 1.6mm and tread heavily damaged (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged small cut not deep enough to reach ply or cord (5.2.3 (d) (ii))

Advice Bonnet release handle damaged

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear (1.1.14 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	28 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



BU20PCX report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

*	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	,
Current registration	UK SIPS
Plate since	
Current registration	UK AIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	5
First mileage registration	2020-03-01
Last registration	2024-02-26
Complete history	See info



Registration #1	2020-03-01	7 mi
Registration #2		11.777 es
Registration #3	2023-02-28	22.905 mi
Registration #4		11.777 es
Registration #5		11.777 es

More info >


CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	94%
Children	87%
Pedestrian	72%
Safety systems	73%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2100 mm
Height	1649 mm
Length	4371 mm
Wheel base	2681 mm
Kerb weight	1712 kg
Max. allowed weight	1841 kg

Additional information

Fuel tank capacity	54 l
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	200122W0614204DTD

CarCheck.co.uk page 11/11