






report date: 2024-03-28

#### General information

Make	CITROEN
Model	BERLINGO 625 ENTERPRISE L1 HDI
Colour	White
Year of manufacture	2012
Top speed	92 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	74 BHP
Max. torque	185 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date	2021-05-28
Pictures	1
Listing price	<u>View report</u>



source: theaa.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-06-16
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	5
Total items failed	3

MOT #11	2023-06-07 11:01
MOT test number	471627093588
Result	✓ Passed
Next expiry date	2024-06-16
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #10	2022-06-14 09:54
MOT test number	578913409392
Result	<b>✓</b> Passed
MOT #9	2021-06-17 10:06
MOT test number	894846147276
Result	<b>✓</b> Passed
MOT #8	2020-06-01 14:35
MOT test number	909796915436
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



DG12HFL

report date: 2024-03-28

MOT #7	2020-06-01 09:17
MOT test number	553760208514
Result	<b>×</b> Failed
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))  Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #6		2019-06-10 09:34
MOT test number		502578770908
Result		✓ Passed
MOT #5		2018-06-11 09:26
MOT test number		101917334575
Result		✓ Passed
MOT #4		2017-06-02 11:50
MOT test number		935985312669
Result		✓ Passed
MOT #3		2017-06-02 11:50
MOT test number		482740020474
Result		<b>★</b> Failed
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	
Pass with rectification	Parking brake lever insecure (3.1.3b)	

CarCheck.co.uk page 4/12



MOT #2 2016-05-25 09:50

**MOT test number** 438760166719

**Result** ✓ Passed

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Nearside Rear Tyre perished

**Advice** Offside Front Tyre worn close to the legal limit 2.8mm and perished also (4.1.E.1)

**MOT #1** 2015-06-04 11:46

**MOT test number** 298895655177

CarCheck.co.uk page 5/12




16 June 2024

See MOT history

Tax & MOT check

**MOT** expiry date

**Full MOT history** 



CarCheck.co.uk page 6/12



DG12HFL

report date: 2024-03-28

#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OEN
***************************************		
***************************************		
*************		
	More info	>
Plate changes  See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		0.00.0
Current registration	UK UK	
Plate since		0.00
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



DG12HFL

report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-03-30
Last registration	2023-06-07
Complete history	See info



Registration #1	2012-03-30	13 mi
Registration #2	2015-06-04	24.555 mi
Registration #3	2016-05-25	29.834 mi
Registration #4	2017-06-02	35.537 mi
Registration #5	2017-06-02	35.537 mi
Registration #6	2018-06-11	39.995 mi
Registration #7	2019-06-10	43.415 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1810 mm
Height	1801 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1385 kg
Max. allowed weight	1945 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBEM0033673

CarCheck.co.uk page 12/12