





report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON GDI SE NAV
Colour	Beige
Year of manufacture	2018
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	132 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-09-10

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-15
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	23
Total items failed	1

MOT #7	2024-03-13 11:19
MOT test number	221219949429
Result	✓ Passed
Next expiry date	2025-03-15
Minor Nearside Rear Position lamp with a multiple light source up to 1, bootlid section (4.2.1 (a) (i))	/2 not functioning upper strip in

MOT #6	2023-03-16 10:07
MOT test number	864251839035
Result	✓ Passed
Advice Under trays fitted obscuring some components for inspection	

MOT #5	2023-03-10	15:53
MOT test	number 2216838	304978
Result	X	Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Under trays fitted obscuring some components for inspection	
MAJOR	Offside Rear Service brake excessively fluctuating (1.2.1 (e))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	

CarCheck.co.uk page 3/12



MOT #4 2022-07-05 13:09

MOT test number 185596644682

Result ✓ Passed

Advice Under-trays fitted at time of test

MOT #3 2022-06-25 07:57

MOT test number 590397019362

Result X Failed

Advice Under-trays fitted at time of test

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Headlamp aim too low (4.1.2 (a))

MAJOR Nearside Headlamp aim too low (4.1.2 (a))

MAJOR Headlamp levelling device inoperative (4.1.5 (a))

MOT #2 2021-06-09 11:59

MOT test number 750655582946

Result ✓ Passed

Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Items removed from driver's view prior to test

Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #1 2021-06-09 11:59

MOT test number 825265463670

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Items removed from driver's view prior to test

Advice Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Owner History	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-08-20
Last registration	2024-03-13
Complete history	See info



Registration #1	2018-08-20	28 mi
Registration #2	2021-06-09	49.468 mi
Registration #3	2021-06-09	49.468 mi
Registration #4		11.777 es
Registration #5	2022-06-25	62.966 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2065 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1414 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	62 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	12/12