





report date: 2024-03-29

## General information

Make	MAZDA
Model	MX-5 RF SPORT NAV
Colour	White
Year of manufacture	2017
Top speed	133 mph
0 - 60 mph	7.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/11



## Internet history

## Entry 2

Date 2024-04-21

Pictures 14

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-03-04
Pictures	12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-03-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #6	2024-03-06 16:54
MOT test number	864511135125
Result	✓ Passed
Next expiry date	2025-03-07
Advice Front pads approx 80% worn	

MOT #5	2023-03-04 07:56
MOT test number	298926724942
Result	<b>✓</b> Passed
Advice Front pads approx 70% worn	

MOT #4		2022-03-08 16:32
MOT test	number	276484781131
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))  Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



MOT #3 2021-07-05 12:19

**MOT test number** 638043414207

Result Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #2** 2021-07-05 12:19

MOT test number 501922812798

**Result** X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #1** 2020-07-13 12:37

MOT test number 370907375786

**Result** 
✓ Passed

CarCheck.co.uk page 4/11



## Tax & MOT check

Tax expired: 19 April 2024





Expires: 7 March 2025

Tax status	Expired at 19 April 2024
Days left	11 days too late
MOT expiry date	7 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	I
First licence fee (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union motory	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	
manus .	
***************************************	
**************************************	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	IK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-07-25
Last registration	2024-03-06
Complete history	See info



Registration #1	2017-07-25	20 mi
Registration #2	2020-07-13	19.998 mi
Registration #3	2021-07-05	22.121 mi
Registration #4	2021-07-05	22.121 mi
Registration #5		9.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



# Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1735 mm
Height	1235 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1045 kg
Max. allowed weight	1295 kg

# Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 31108372

CarCheck.co.uk page 11/11