



report date: 2024-03-29

General information

Make	FORD
Model	KUGA LX TDCI
Colour	Black
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-01-31
Pictures	0
Listing price	<a href="#">View report</a>

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #17	2023-10-03 08:39
MOT test number	388840277777
Result	✓ Passed
Next expiry date	2024-10-05
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Central Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2022-10-06 15:05

**MOT test number**

252724252403

**Result**

✓ Passed

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #15**

2022-09-29 15:15

**MOT test number**

525891314714

**Result**

✗ Failed

- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear calliper / cable binding
- Advice** Offside Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Brake lever pivot has excessive wear or free play hand break has too much travel (1.1.1 (b))
- Fail** Brake performance not tested (1.2.1 (g))

**MOT #14** 2021-09-10 13:32**MOT test number** 649125823534**Result** Passed

- Advice** Covers fitted to vehicle unable to facilitate full inspection
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases middle section (6.1.2 (a))

**MOT #13** 2020-10-01 13:52**MOT test number** 938043434411**Result** Passed**MOT #12** 2020-09-30 09:36**MOT test number** 930907606512**Result** Failed

- Fail** Exhaust emissions likely to be affected by an exhaust leak dpf cracked/holed (8.2.2.1 (b))
- Advice** Front cat bolts missing
- Advice** Offside Rear tyre slightly distorted

**MOT #11** 2019-09-19 10:04**MOT test number** 216599969273**Result** Passed**MOT #10** 2018-09-29 09:48**MOT test number** 711266493841**Result** Passed

**MOT #9** 2017-09-29 14:18**MOT test number** 522990686944**Result** ✓ Passed**MOT #8** 2016-10-03 13:48**MOT test number** 524716070820**Result** ✓ Passed**MOT #7** 2016-10-03 12:02**MOT test number** 686252021512**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**MOT #6** 2016-07-18 15:03**MOT test number** 369118945990**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-07-17 11:20**MOT test number** 778818095104**Result** ✓ Passed**MOT #4** 2014-07-16 16:26**MOT test number** 215247494444**Result** ✓ Passed**MOT #3** 2013-07-17 16:51**MOT test number** 878848293199**Result** ✓ Passed



MOT #2	2012-07-18 14:31
MOT test number	408590602251
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2011-07-18 16:05
MOT test number	907699791131
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
5 October 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	5 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-19
Last registration	2023-10-03
Complete history	<a href="#">See info</a>



Registration #1	2008-07-19	25 mi
Registration #2	2011-07-18	25.424 mi
Registration #3	2012-07-18	35.799 mi
Registration #4	2013-07-17	42.599 mi
Registration #5	2014-07-16	49.997 mi
Registration #6	2015-07-17	57.119 mi
Registration #7	2016-07-18	63.399 mi
Registration #8	2016-10-03	63.938 mi
Registration #9	2016-10-03	63.938 mi
Registration #10	2017-09-29	78.101 mi
Registration #11	2018-09-29	93.377 mi
Registration #12	2019-09-29	108.653 mi
Registration #13	2020-09-29	123.929 mi
Registration #14	2021-09-29	139.205 mi
Registration #15	2022-09-29	154.481 mi
Registration #16	2023-09-29	169.757 mi
Registration #17	2024-09-29	185.033 mi
Registration #18	2025-09-29	200.309 mi
Registration #19	2026-09-29	215.585 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	8R41969