



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 GDI STYLE
Colour	Silver
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	164 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	155 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	26
Total items failed	7

MOT #11	2023-06-15 07:46
MOT test number	715483862811
Result	✓ Passed
Next expiry date	2024-06-29
Advice	Coil spring corroded Both rear coil springs corroded (5.3.1 (b) (i))
Advice	Coil spring corroded Both front coil springs corroded (5.3.1 (b) (i))
Advice	Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))

MOT #10	2023-06-14 10:23
MOT test number	856823291888
Result	✗ Failed
Advice	Exhaust has a minor leak of exhaust gases Back box (6.1.2 (a))
Advice	Coil spring corroded Both rear coil springs corroded (5.3.1 (b) (i))
Fail	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Coil spring corroded Both front coil springs corroded (5.3.1 (b) (i))
Fail	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #9** 2022-06-29 11:14**MOT test number** 143529129338**Result** ✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases Back box seam slight leak (6.1.2 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

MOT #8 2021-06-30 06:20**MOT test number** 542354830024**Result** ✓ Passed

- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Under tray fitted

MOT #7 2021-06-28 14:08**MOT test number** 797828881260**Result** ✗ Failed

- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Under tray fitted
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Fail** Rear Reversing lamp inoperative (4.6.1 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Central Front Exhaust has a minor leak of exhaust gases flexi (6.1.2 (a))

**MOT #6** 2019-09-12 13:04**MOT test number** 650076233156**Result** ✓ Passed**Advice** Engine covers and under trays fitted**Advice** O/s and n/s lower suspension arm washer weights loose**MOT #5** 2018-10-02 09:00**MOT test number** 371086096466**Result** ✓ Passed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement anti vibration washer loose (5.3.4 (a) (i))**Advice** Under trays and engine covers fitted**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement anti vibration washer bush detached (5.3.4 (a) (i))**MOT #4** 2017-10-02 10:04**MOT test number** 939781770180**Result** ✓ Passed**MOT #3** 2017-10-02 08:37**MOT test number** 686111765038**Result** ✗ Failed**Fail** Front registration plate deteriorated (6.3.1d)



MOT #2	2016-10-27 09:03
MOT test number	709997157956
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Under trays fitted
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #1	2015-11-12 10:10
MOT test number	423300665049
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-11-27
Last registration	2023-06-15
Complete history	See info



Registration #1	2012-11-27	7 mi
Registration #2	2015-11-12	37.580 mi
Registration #3	2016-10-27	49.228 mi
Registration #4	2017-10-02	61.478 mi
Registration #5	2017-10-02	61.478 mi
Registration #6	2018-10-02	75.135 mi
Registration #7	2019-09-12	88.503 mi
Registration #8	2019-09-12	88.503 mi
Registration #9	2019-09-12	88.503 mi
Registration #10	2019-09-12	88.503 mi
Registration #11	2019-09-12	88.503 mi
Registration #12	2019-09-12	88.503 mi
Registration #13	2019-09-12	88.503 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1534 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FDCU642564