



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 16V
Colour	Black
Year of manufacture	2008
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-09
Pictures	4
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2022-09-30
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	56
Total items failed	7

MOT #16	2021-10-01 14:04
MOT test number	875530507620
Result	✓ Passed
Next expiry date	2022-09-30

MOT #15	2020-08-21 11:57
MOT test number	418814057561
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2020-08-20 14:53

**MOT test number**

987212940471

**Result****✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Brake fluid warning lamp illuminated (1.1.10 (f))**MAJOR** Brake fluid significantly below minimum mark (1.1.10 (d) (ii))**MAJOR** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #13**

2019-09-02 14:22

**MOT test number**

761233240570

**Result****✓ Passed****Advice** Offside Rear Tyre worn close to legal limit/worn on edge getting low (5.2.3 (e))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning top bulb not working (4.2.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2019-09-02 09:43

**MOT test number**

807370121582

**Result****✗ Failed**

**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning top bulb not working (4.2.1 (a) (i))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge getting low (5.2.3 (e))

**MAJOR** Exhaust emits clearly visible black smoke during acceleration (8.2.1.2 (g))

**MOT #11**

2018-08-30 08:51

**MOT test number**

644751461143

**Result****✓ Passed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Suspension component pin or bush slightly worn MARKED IN CHALK (5.3.4 (a) (i))

**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** BOTH REAR BRAKE HOSE ENDS CORRODED

**Advice** Nearside Rear Suspension component pin or bush slightly worn MARKED IN CHALK (5.3.4 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #10**

2017-09-01 08:20

**MOT test number**

290982214568

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** WINTER TYRES FITTED TO REAR
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Brake pipe slightly corroded FRONT TO REAR (3.6.B.2c)
- Advice** Offside Front Tyre worn close to the legal limit TYRE ALSO HAS MAJOR REPAIR (4.1.E.1)
- Advice** Nearside Brake pipe slightly corroded FRONT TO REAR (3.6.B.2c)

**MOT #9**

2016-09-05 11:42

**MOT test number**

501669709162

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine covers obscuring some components
- Advice** Under trays obscuring some components

**MOT #8**

2015-08-05 13:35

**MOT test number**

399867815235

**Result**

✓ Passed

**MOT #7**

2015-08-05 12:00

**MOT test number**

547417715258

**Result****✗ Failed**

- Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Surface rust on brake pipes
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Coil spring broken (2.4.C.1a)

**MOT #6**

2015-01-24 09:40

**MOT test number**

429104725004

**Result****✗ Failed**

- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Nearside Rear Stop lamp has less than 50% of the light sources illuminating (1.2.1b)
- Fail** Nearside Rear coil spring broken (2.4.C.1a)
- Advice** Offside Front Brake hose slightly chafed (3.6.B.4d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Notice** Engine temperature gauge inop

**MOT #5** 2014-02-01 09:17**MOT test number** 519332834079**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2013-02-01 15:48**MOT test number** 255522333000**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2013-02-01 09:26**MOT test number** 558412333059**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-02-08 17:10**MOT test number** 727249332041**Result** ✓ Passed**MOT #1** 2011-09-09 15:19**MOT test number** 967052351293**Result** ✓ Passed





Tax & MOT check

✕  
Untaxed

Tax expired:  
31 December 2021

✕  
MOT

Expired:  
30 September 2022

Tax status	Expired at 31 December 2021
Days left	851 days too late
MOT expiry date	30 September 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>VAUXH</b>
Plate since	2024-03-29
Current registration	<b>VAUXH</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2021-10-01
Complete history	<a href="#">See info</a>



Registration #1	2008-09-30	26 mi
Registration #2	2011-09-09	13.075 mi
Registration #3	2012-02-08	14.707 mi
Registration #4	2013-02-01	26.387 mi
Registration #5	2013-02-01	26.387 mi
Registration #6	2014-02-01	38.488 mi
Registration #7	2015-01-24	52.131 mi
Registration #8	2015-08-05	60.898 mi
Registration #9	2015-08-05	60.898 mi
Registration #10	2015-08-05	60.898 mi
Registration #11	2015-08-05	60.898 mi
Registration #12	2015-08-05	60.898 mi
Registration #13	2015-08-05	60.898 mi
Registration #14	2015-08-05	60.898 mi
Registration #15	2015-08-05	60.898 mi
Registration #16	2015-08-05	60.898 mi
Registration #17	2015-08-05	60.898 mi
Registration #18	2015-08-05	60.898 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17390132