



AJ09MHX

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	GOLF GT TDI
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-10-29
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	33
Total items failed	7

MOT #15 2023-10-30 13:41

MOT test number 719607673709

Result ✓ Passed

Next expiry date 2024-10-29

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2022-03-24 16:32

MOT test number 542267138695

Result ✓ Passed

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced both rear inner seals (6.1.1 (c) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13** 2021-06-03 07:51**MOT test number** 972191058406**Result** ✓ Passed**Advice** Surface corrosion under vehicle**MOT #12** 2020-11-12 15:18**MOT test number** 622061371226**Result** ✓ Passed**MOT #11** 2020-11-04 16:07**MOT test number** 471572662473**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #10** 2019-06-12 11:30**MOT test number** 332997001703**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2018-06-18 12:22**MOT test number** 907867416329**Result** ✓ Passed**Advice** Covers fitted to underside of vehicle

**MOT #8** 2018-06-11 11:56**MOT test number** 338783771119**Result** ✗ Failed**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Covers fitted to underside of vehicle**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #7** 2017-06-20 13:16**MOT test number** 204395673438**Result** ✓ Passed**Advice** Nearside rear shock absorber dust cover loose**Advice** Offside outer sill has slight surface damage**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Covers fitted to underside of vehicle**MOT #6** 2017-06-16 11:50**MOT test number** 920048573798**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Covers fitted to underside of vehicle**Fail** Offside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Nearside rear shock absorber dust cover loose**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Offside outer sill has slight surface damage

**MOT #5** 2016-06-14 13:14**MOT test number** 192762482100**Result** ✓ Passed**Advice** Crack in screen at bottom**Advice** Under trays fitted**MOT #4** 2015-06-17 12:09**MOT test number** 836538065190**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Both front tyres wearing outer edges**MOT #3** 2014-06-10 11:18**MOT test number** 296981464199**Result** ✓ Passed**Notice** Windscreen cracked at the bottom not in drivers view**MOT #2** 2013-06-21 09:22**MOT test number** 229772373158**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** No emission results to clean**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Under-trays fitted obscuring some underside components**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-06-15 14:32
--------	------------------

MOT test number	585347562164
-----------------	--------------

Result	✓ Passed
--------	----------

- Notice** Front wiper blades splitting but still clearing the screen.
- Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXX
Plate since	2024-03-28
Current registration	 XXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-04-28
Last registration	2023-10-30
Complete history	See info



Registration #1	2009-04-28	11 mi
Registration #2	2012-06-15	24.746 mi
Registration #3	2013-06-21	32.301 mi
Registration #4	2014-06-10	39.909 mi
Registration #5	2015-06-17	45.818 mi
Registration #6	2016-06-14	52.730 mi
Registration #7	2017-06-16	59.858 mi
Registration #8	2017-06-20	59.860 mi
Registration #9	2018-06-20	59.860 mi
Registration #10	2019-06-20	59.860 mi
Registration #11	2020-06-20	59.860 mi
Registration #12	2021-06-20	59.860 mi
Registration #13	2022-06-20	59.860 mi
Registration #14	2023-06-20	59.860 mi
Registration #15	2023-10-30	59.860 mi
Registration #16	2024-03-28	59.860 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	CBA 494126