



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2013
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-27
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-12-30
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #11	2023-12-12 16:17
MOT test number	489568565884
Result	✓ Passed
Next expiry date	2024-12-30
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10	2022-12-08 16:56
MOT test number	415283444487
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9	2021-12-31 12:39
MOT test number	508351338109
Result	✓ Passed

**MOT #8** 2020-12-10 13:45**MOT test number** 784103598661**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Slight sidewall damage (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Cracking inner edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Slight sidewall damage (5.2.3 (e))**MOT #7** 2020-12-10 09:03**MOT test number** 351702949653**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Slight sidewall damage (5.2.3 (e))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure Inner sidewall (5.2.3 (d) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Slight sidewall damage (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Cracking inner edge (5.2.3 (e))**MOT #6** 2019-11-30 14:59**MOT test number** 115501243198**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Emissions too clean to test**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2019-11-30 09:17**MOT test number** 170562842007**Result** ✗ Failed**Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall (5.2.3 (d) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Emissions too clean to test**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2018-11-01 15:11**MOT test number** 592180110342**Result** ✓ Passed**MOT #3** 2018-10-18 14:02**MOT test number** 319938548620**Result** ✗ Failed**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MOT #2** 2017-11-13 10:42**MOT test number** 905466659563**Result** ✓ Passed



MOT #1	2016-11-18 14:05
MOT test number	631144932168
Result	✓ Passed
<div><div>Advice</div>Rear brake disc worn, pitted or scored, but not seriously weakened offside and nearside corroded/pitted slightly (3.5.1i)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
30 December 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	30 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>YC63JKJ</b>
Plate since	2019-09-29
Current registration	<b>YC63JKJ</b>
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-15
Last registration	2023-12-12
Complete history	<a href="#">See info</a>



Registration #1	2013-10-15	9 mi
Registration #2	2016-11-18	43.010 mi
Registration #3	2017-11-13	57.631 mi
Registration #4	2018-10-18	68.967 mi
Registration #5	2018-11-01	68.970 mi
Registration #6	2019-11-30	82.147 mi
Registration #7	2019-11-30	82.147 mi
Registration #8	2019-11-30	82.147 mi
Registration #9	2019-11-30	82.147 mi
Registration #10	2019-11-30	82.147 mi
Registration #11	2019-11-30	82.147 mi
Registration #12	2019-11-30	82.147 mi
Registration #13	2019-11-30	82.147 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CFHC521033