





report date: 2024-03-28

#### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY TCE S/S
Colour	White
Year of manufacture	2014
Top speed	124 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	130 BHP
Max. torque	205 Nm at 2.000 rpm
Engine capacity	1.198 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	44.1 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

### Internet history


#### Entry 2

Date 2022-01-14

Pictures 12

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date	2022-01-11
Pictures	16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-03-14
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	20
Total items failed	1

MOT #12		2024-02-27 09:33
<b>MOT</b> test	number	320651543753
Result		<b>✓</b> Passed
Next expi	ry date	2025-03-14
Advice	Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b)	(i))
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (	b) (i))

MOT #11	2023-03-15 13:19
MOT test number	716326080216
Result	✓ Passed

MOT #10	2023-03-15 09:54
MOT test number	271946055302
Result	<b>X</b> Failed
DANGEROUS (d) (ii))	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3
<b>DANGEROUS</b> (d) (ii))	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3
<b>DANGEROUS</b> (d) (ii))	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3

MOT #9	2022-03-15 10:31
MOT test number	703140068881
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2022-03-14 17:11

**MOT test number** 149665824320

Result × Failed

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #7 2021-09-24 07:44

MOT test number 290007726650

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2021-09-17 15:08

**MOT test number** 110582091663

Result X Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #5 2020-09-09 15:10

MOT test number 823271777853

Result 

Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2019-09-06 13:35

MOT test number 388553133106

**Result** 
✓ Passed

**MOT #3** 2018-09-13 15:42


**MOT test number** 438460433982

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28





CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	14 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

# Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-30
Last registration	2024-02-27
Complete history	See info



Registration #1	2014-09-30	29 mi
Registration #2	2017-09-25	25.631 mi
Registration #3	2017-09-25	25.631 mi
Registration #4	2018-09-13	30.149 mi
Registration #5	2019-09-06	36.853 mi
Registration #6	2020-09-09	42.875 mi
Registration #7	2021-09-17	47.219 mi
Registration #8	2021-09-24	47.219 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		91.777 esi
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 11/12



BU64WVV report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

# Safety ratings

NCAP rating	***
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	48%
Overall rating	71%
Video	see crash video



# Dimensions & weight

Width	1811 mm
Height	1434 mm
Length	4485 mm
Wheel base	2609 mm
Kerb weight	1547 kg
Max. allowed weight	1960 kg

# Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	4 page 1:	2/12

Number of axles 2
Engine number D026954