





report date: 2024-03-29

General information

Make	FORD
Model	FUSION FUSION +
Colour	Silver
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-20

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-12-14
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	14
Total items failed	2

MOT #13		2023-12-11 10:16
MOT test	number	358665182019
Result		✓ Passed
Next expiry date 2024-13		2024-12-14
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))		
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #12		2023-12-11 10:16
MOT test number		616708974482
Result		X Failed
Pass with rectification	Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))		
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))		

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #11 2022-12-15 10:25

MOT test number 997150957082

Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

MOT #10 2022-12-15 10:25

MOT test number 985368664777

Result X Failed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Nearside Front Tyre slightly damaged/cracking or perishing perishing in the tread. (5.2.3 (d) (ii))

MOT #9 2022-02-02 17:32

MOT test number 101407725489

Result ✓ Passed

MOT #8 2019-09-09 12:26

MOT test number 743961651684

Result
✓ Passed

MOT #7 2018-09-18 12:43

MOT test number 571431603279

CarCheck.co.uk page 4/12



MOT test number

Result

Advice

YD59PMY

report date: 2024-03-29

456007664259

✓ Passed

MOT #6	2017-09-11 09:03
MOT test number	893912921118
Result	✓ Passed
MOT #5	2016-09-07 13:59
MOT test number	325322775084
Result	✓ Passed
MOT #4	2015-09-22 13:45
MOT test number	724825440482
Result	✓ Passed
MOT #3	2014-09-24 10:11

MOT #2	2013-09-11 08:58
MOT test number	386884553493
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #1	2012-09-26 08:49
MOT test number	279990572248
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report J	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-29
Last registration	2023-12-11
Complete history	See info



Registration #1	2009-09-29	11 mi
Registration #2	2012-09-26	13.904 mi
Registration #3	2013-09-11	18.839 mi
Registration #4	2014-09-24	24.583 mi
Registration #5	2015-09-22	29.490 mi
Registration #6	2016-09-07	32.442 mi
Registration #7	2017-09-11	34.461 mi
Registration #8	2018-09-18	36.235 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		70,777 au

More info >

CarCheck.co.uk page 11/12



YD59PMY report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2
Engine number 9P21532