

Ford



General information

Make	FORD
Model	TRANSIT CONNECT TREND TDCI
Colour	Silver
Year of manufacture	2010
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP	0 < 101 A
Max. torque	240 Nm at 1.750 rpm	101 - 120 B
Engine capacity	1.753 cc	121 - 140 P
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185 H
Consumption city	35.8 mpg	186 - 225 J
Consumption extra urban	51.4 mpg	225+ L
Consumption combined	44.1 mpg	
CO2 emission	168 g/km	
CO2 label	Н	





Internet history


Entry 2

Date Pictures 2021-06-30

10

Listing price

View report



source: cargurus.co.uk

Entry 1	
Date	2021-05-26
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-11-14
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	14
Total items failed	9

MOT #15	2023-11-14 17:08
MOT test number	155717396648
Result	✓ Passed
Next expiry date	2024-11-14

MOT #14	2022-11-07 16:27
MOT test number	278503363421
Result	🗸 Passed
Advice Covers impede parts of the inspection.	

MOT #13	2021-11-15 08:50
MOT test number	354098508413
Result	✓ Passed

MOT #12		2021-02-03 16:55
MOT test	number	528952806649
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	All suspension and brake components have surface corossion	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #11	2020-01-07 12:57	
MOT test number	325443214893	
Result	✓ Passed	
MOT #10	2019-12-31 10:29	
MOT test number	953281351014	
Result	🗙 Failed	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))	
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))		
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))		

MOT #9	2	018-11-15 11:39
MOT test	number	729890900839
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8		2017-11-03 08:51
MOT test	number	584342739339
Result		Passed
Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)	



RX10DZL report date: 2024-03-28

MOT #7	2017-11-03 08:51
MOT test number	545132303367
Result	🗙 Failed
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)
Pass with rectification Nearside Windscreen wiper does not	ot clear the windscreen effectively (8.2.2)
Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)	
Pass with rectification Offside Windscreen wiper does not	clear the windscreen effectively (8.2.2)
МОТ #6	2016-06-03 07:52
MOT test number	429998743148
Result	✓ Passed
MOT #5	2015-04-22 15:16
MOT test number	278042315187
Result	✓ Passed
МОТ #4	2015-04-22 09:10
MOT test number	488572015158

🗙 Failed

MOT #3	2014-05-20 09:21
MOT test number	299630944178
Result	✓ Passed
Advice Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a))





MOT #2	2013-04-30 11:55
MOT test number	656210523114
Result	✓ Passed
MOT #1	2013-04-30 11:55
MOT test number	768440623158
Result	× Failed
Pass with rectification	Offside Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

✓ Taxed	✓ MOT Expires:
1 December 2024 Tax status	14 November 2024 Valid until 1 December
Days left	217
MOT expiry date	14 November 2024
Full MOT history	<u>See MOT history</u>

Tax calculation

Vehicle class	49
Band	н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-25
Last registration	2023-11-14
Complete history	<u>See info</u>



Registration #1	2010-05-25	14 mi
Registration #2	2013-04-30	26.478 mi
Registration #3	2014-05-20	34.925 mi
Registration #4	2015-04-22	42.299 mi
Registration #5	2015-04-22	42.299 mi
Registration #6	2016-06-03	43.999 mi
Registration #7	2017-11-03	44.075 mi
Registration #8	2017-11-03	44.075 mi
Registration #9	2018-11-15	44.097 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 est





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	2044 mm
Height	1981 mm
Length	4525 mm
Max. allowed weight	2330 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	AU68636