



YT09ZXV


report date: 2024-03-29

General information

Make	FIAT
Model	GRANDE PUNTO 16V GP
Colour	Yellow
Year of manufacture	2009
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	125 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-04
Pictures	17
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-09-30
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	23
Total items failed	7

MOT #15 2021-09-28 13:20**MOT test number** 995920864103**Result** ✓ Passed**Next expiry date** 2022-09-30

- Advice** Exhaust flex pipe worn
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust system corroded

MOT #14 2021-09-28 13:20**MOT test number** 760581209635**Result** ✗ Failed

- Advice** Exhaust flex pipe worn
- Advice** Exhaust system corroded
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-10-01 13:12**MOT test number** 750369375812**Result** ✓ Passed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2020-09-25 14:29**MOT test number** 868169014395**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11** 2019-04-12 15:33**MOT test number** 400734020165**Result** ✓ Passed**MOT #10** 2019-04-12 11:58**MOT test number** 409435755044**Result** ✗ Failed**Advice** Front Direction indicator slightly discoloured Both (4.4.3 (a))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #9** 2018-04-19 11:00**MOT test number** 582963986374**Result** ✓ Passed

**MOT #8** 2017-02-24 16:52**MOT test number** 341074508446**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Items removed from driver's view prior to test**MOT #7** 2017-02-24 10:15**MOT test number** 419095663106**Result** ✗ Failed**Fail** Steering lock fails to engage (2.1.4b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Items removed from driver's view prior to test**MOT #6** 2016-03-08 12:06**MOT test number** 482629143955**Result** ✓ Passed**Advice** Rear tyres**Advice** Exhaust corroded

**MOT #5** 2015-12-02 09:01**MOT test number** 840803954362**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**Advice** Rear exhaust outer casing**Advice** N/s front blade**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Heat shield loose rear**MOT #4** 2014-11-11 11:46**MOT test number** 386945114306**Result** ✓ Passed**MOT #3** 2013-11-19 14:21**MOT test number** 469133823326**Result** ✓ Passed**MOT #2** 2013-03-06 13:42**MOT test number** 785985563048**Result** ✓ Passed**MOT #1** 2012-03-14 12:56**MOT test number** 805884772049**Result** ✓ Passed**Notice** Items removed from driver's view prior to test



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-19
Last registration	2021-09-28
Complete history	See info



Registration #1	2009-03-19	22 mi
Registration #2	2012-03-14	24.813 mi
Registration #3	2013-03-06	31.854 mi
Registration #4	2013-11-19	35.033 mi
Registration #5	2014-11-11	42.072 mi
Registration #6	2015-12-02	49.156 mi
Registration #7	2016-03-08	49.972 mi
Registration #8	2017-02-24	64.942 mi
Registration #9	2017-02-24	64.944 mi
Registration #10	2018-03-01	75.377 mi
Registration #11	2018-03-01	75.377 mi
Registration #12	2018-03-01	75.377 mi
Registration #13	2018-03-01	75.377 mi
Registration #14	2018-03-01	75.377 mi
Registration #15	2018-03-01	75.377 mi
Registration #16	2018-03-01	75.377 mi
Registration #17	2018-03-01	75.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	1358123