



TOYOTA

SM6IH XU

report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO D-4D TR
Colour	Black
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg





Internet history

Entry 1

Date	2021-08-05
Pictures	30
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #13	2022-10-21 09:38
MOT test number	240935671292
Result	✓ Passed
Next expiry date	2023-10-24
Advice	Handbrake lever travels
Advice	Offside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Under of vehicle undersealed
Advice	Nearside Rear Body not fully secure body slightly damaged (6.2.2 (a) (i))

MOT #12	2021-10-12 15:57
MOT test number	115824480324
Result	✓ Passed

MOT #11	2020-10-09 07:55
MOT test number	529506771365
Result	✓ Passed

MOT #10	2020-10-08 11:17
MOT test number	306401403137
Result	✗ Failed
Fail	Horn not working (7.7 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2019-10-25 13:46
MOT test number	936712115629
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2019-10-25 08:11**MOT test number** 580295428810**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Both rears (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material BOTH FRONT TO REARS (1.1.11 (c))

MOT #7 2019-01-16 15:49**MOT test number** 272085535135**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))

MOT #6 2019-01-15 09:18**MOT test number** 175386456162**Result** ✗ Failed

- Fail** Horn not working (7.7 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner edge (5.2.3 (e))

**MOT #5**

2017-10-31 09:25

MOT test number

864507444396

Result

✓ Passed

- Advice** Exhaust bracket broken at middle section but still adequately supported
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Nail in tyre
- Advice** Exhaust has a minor leak of exhaust gases Middle to rear section joint (7.1.2)

MOT #4

2016-11-07 13:54

MOT test number

140169697621

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

MOT #3

2015-11-18 12:49

MOT test number

901693801379

Result

✓ Passed

MOT #2

2014-11-13 12:00

MOT test number

677267614338

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2014-11-13 12:00
MOT test number	118527314334
Result	✗ Failed
Pass with rectification	Rear registration plate insecure (6.3.1b)
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-09
Last registration	2022-10-21
Complete history	See info



Registration #1	2011-12-09	28 mi
Registration #2	2014-11-13	51.154 mi
Registration #3	2015-11-18	65.906 mi
Registration #4	2016-11-07	84.093 mi
Registration #5	2017-10-31	97.568 mi
Registration #6	2019-01-15	115.606 mi
Registration #7	2019-01-16	115.609 mi
Registration #8	2019-01-16	115.609 mi
Registration #9	2019-01-16	115.609 mi
Registration #10	2019-01-16	115.609 mi
Registration #11	2019-01-16	115.609 mi
Registration #12	2019-01-16	115.609 mi
Registration #13	2019-01-16	115.609 mi
Registration #14	2019-01-16	115.609 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1625 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1AD5602172