



report date: 2024-03-29

General information

Make	FIAT
Model	DOBLO 8V ACTIVE
Colour	Green
Year of manufacture	2009
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 2




Date	2022-02-11
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-27
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-02
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	34
Total items failed	14

MOT #21	2024-02-14 14:39
MOT test number	944637383342
Result	✓ Passed
Next expiry date	2025-03-02
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner faces heavily scored and pitted (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #20	2024-02-14 13:36
MOT test number	662077909556
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner faces heavily scored and pitted (1.1.14 (a) (ii))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
MAJOR	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #19	2023-03-03 13:10
MOT test number	679222884329
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18** 2023-03-02 15:52**MOT test number** 788033219676**Result** ✗ Failed**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2021-09-28 10:15**MOT test number** 178784513396**Result** ✓ Passed**Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #16** 2021-09-28 10:15**MOT test number** 759169139271**Result** ✗ Failed**Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Pass with rectification** Offside Obligatory mirror insecure (3.3 (b) (ii))**MOT #15** 2020-09-14 14:03**MOT test number** 181686128313**Result** ✓ Passed

**MOT #14** 2020-09-11 07:48**MOT test number** 696124858490**Result** ✗ Failed

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Nearside Front Lower Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Rear Other passenger door cannot be opened from outside the vehicle Boot (6.2.3 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge & perishing (5.2.3 (e))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #13 2019-09-06 09:11**MOT test number** 318537782400**Result** ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12 2018-08-23 14:43**MOT test number** 140607995599**Result** ✓ Passed

Advice Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))

Advice Nearside Non obligatory mirror damaged

**MOT #11** 2018-08-23 10:20**MOT test number** 345444505093**Result** ✗ Failed**MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Non obligatory mirror damaged**MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bushes (5.3.4 (a) (i))**MOT #10** 2017-09-12 09:11**MOT test number** 531295657863**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**MOT #9** 2017-08-22 10:11**MOT test number** 862726847909**Result** ✗ Failed**Fail** Power steering fluid level below minimum (2.3.1)**Fail** Nearside Headlamp aim too high (1.8)**Advice** Nearside Non obligatory mirror damaged**Fail** Power steering component(s) leaking Rack (2.3.3b)**Fail** Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)**Fail** Offside Headlamp aim too high (1.8)**MOT #8** 2016-08-18 09:21**MOT test number** 371039939899**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2016-08-18 09:07**MOT test number** 542318865062**Result** ✗ Failed**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Headlamp aim too high (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Headlamp aim too high (1.8)**MOT #6** 2015-08-25 10:50**MOT test number** 994320906567**Result** ✓ Passed**MOT #5** 2015-08-25 10:50**MOT test number** 635330376817**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2014-08-18 16:09**MOT test number** 188380534219**Result** ✓ Passed**MOT #3** 2014-08-18 10:25**MOT test number** 365300534472**Result** ✗ Failed**Fail** Power steering component(s) leaking (2.3.3b)



MOT #2	2013-08-29 14:34
MOT test number	207451443202
Result	✓ Passed
Notice	Offside steering rack gaiter damp
Notice	Offside and centre rear seats missing
Notice	Nearside front tyre close to limit

MOT #1	2012-09-19 17:28
MOT test number	965163062282
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
2 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	2 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2009-11-18
Last registration	2024-02-14
Complete history	See info



Registration #1	2009-11-18	27 mi
Registration #2	2012-09-19	8.226 mi
Registration #3	2013-08-29	16.005 mi
Registration #4	2014-08-18	23.351 mi
Registration #5	2014-08-18	23.352 mi
Registration #6	2015-08-25	32.260 mi
Registration #7	2015-08-25	32.260 mi
Registration #8	2016-08-18	38.918 mi
Registration #9	2016-08-18	38.918 mi
Registration #10	2017-08-22	40.599 mi
Registration #11	2017-09-12	40.602 mi
Registration #12	2018-08-23	48.927 mi
Registration #13	2019-08-23	55.337 mi
Registration #14	2019-08-23	55.337 mi
Registration #15	2019-08-23	55.337 mi
Registration #16	2019-08-23	55.337 mi
Registration #17	2019-08-23	55.337 mi
Registration #18	2019-08-23	55.337 mi
Registration #19	2019-08-23	55.337 mi
Registration #20	2019-08-23	55.337 mi
Registration #21	2019-08-23	55.337 mi
Registration #22	2019-08-23	55.337 mi
Registration #23	2019-08-23	55.337 mi
Registration #24	2019-08-23	55.337 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

5055820