




report date: 2024-09-18

General information

Make	MINI
Model	CLUBVAN COOPER D
Colour	White
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	103 g/km
CO2 label	B





## Internet history

### Entry 1

Date	2021-06-14
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT expiry date</b>	2024-05-15
<b>MOT pass rate</b>	89 %
<b>MOT passed</b>	8
<b>Failed MOT tests</b>	1
<b>Total advice items</b>	6
<b>Total items failed</b>	1

<b>MOT #9</b>	2023-05-16 14:44
<b>MOT test number</b>	563285075229
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-05-15

<b>MOT #8</b>	2022-04-27 09:22
<b>MOT test number</b>	653091583392
<b>Result</b>	✓ Passed
<b>Advice</b>	Vehicles internal headlight adjuster altered to recheck lights

<b>MOT #7</b>	2021-04-24 08:09
<b>MOT test number</b>	552056322145
<b>Result</b>	✓ Passed
<b>Minor</b>	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



<b>MOT #6</b>	2020-05-16 12:36
<b>MOT test number</b>	656859039966
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear brake discs worn.
<b>Advice</b>	Offside Rear Tyre cracked.
<b>Advice</b>	Nearside Rear Tyre wearing low and cracked.
<b>Advice</b>	Under trays fitted on.

<b>MOT #5</b>	2019-06-10 10:10
<b>MOT test number</b>	672164155555
<b>Result</b>	✓ Passed

<b>MOT #4</b>	2018-06-12 12:44
<b>MOT test number</b>	244715810961
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2018-06-12 12:44
<b>MOT test number</b>	881495221873
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Stop lamp(s) not working (4.3.1 (a) (ii))

<b>MOT #2</b>	2017-06-22 07:51
<b>MOT test number</b>	878430280981
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2017-02-14 10:14
<b>MOT test number</b>	214234672379
<b>Result</b>	✓ Passed



Tax & MOT check

**×**  
**Untaxed**

**Tax expired:**  
26 July 2023

**×**  
**MOT**

**Expired:**  
15 May 2024

**Tax status** Expired at 26 July 2023

**Days left** 444 days too late

**MOT expiry date** 15 May 2024

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-




**Damage history**

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra MINI salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>FM13FUE</b>
Plate since	2019-09-18
Current registration	<b>FM13FUE</b>
Plate since	2019-09-18

More info >





**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-08-01
Last registration	2023-05-16
Complete history	<a href="#">See info</a>



Registration #1	2013-08-01	20 mi
Registration #2	2017-02-14	28.172 mi
Registration #3	2017-06-22	32.099 mi
Registration #4	2018-06-12	40.163 mi
Registration #5	2018-06-12	40.163 mi
Registration #6	2019-06-10	44.429 mi
Registration #7	2019-06-10	44.429 mi
Registration #8	2019-06-10	44.429 mi
Registration #9	2019-06-10	44.429 mi
Registration #10	2019-06-10	44.429 mi
Registration #11	2019-06-10	44.429 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Kerb weight	1185 kg
Max. allowed weight	1685 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	76708710