



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 TDI KOMBI HIGHLINE
Colour	Purple
Year of manufacture	2014
Top speed	108 mph
0 - 100 km/h	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-11-08
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-22
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-31
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	37
Total items failed	5

MOT #11	2024-01-10 11:02
MOT test number	321524133983
Result	✓ Passed
Next expiry date	2025-01-31
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #10	2023-01-26 09:30
MOT test number	664956414120
Result	✓ Passed

MOT #9	2022-02-01 16:09
MOT test number	479797507942
Result	✓ Passed

**MOT #8**

2022-01-25 16:24

MOT test number

143948369230

Result**✗ Failed**

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Fail Nearside Rear Road wheel fractured (5.2.2 (a))

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))



MOT #7

2021-03-15 11:12

MOT test number

830020705410

Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

**MOT #6**

2021-03-11 15:42

MOT test number

340512004991

Result**✗ Failed**

- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #5

2020-03-09 14:52

MOT test number

679236564057

Result**✓ Passed**

- Advice** Nearside Front Steering rack has slight free play detected at steering wheel track rod + inner tie rod (2.3 (a) (i))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel track rod + inner tie rod (2.3 (a) (i))

**MOT #4** 2020-03-06 15:36**MOT test number** 955284674514**Result** ✗ Failed

Advice Offside Front Steering rack has slight free play detected at steering wheel track rod + inner tie rod (2.3 (a) (i))

Advice Nearside Front Steering rack has slight free play detected at steering wheel track rod + inner tie rod (2.3 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps (4.7.1 (b) (ii))

MOT #3 2019-03-16 12:05**MOT test number** 801821213716**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #2 2018-01-25 12:18**MOT test number** 936244825779**Result** ✓ Passed

Advice Front suspension arm bushes have slight play

MOT #1 2017-01-24 10:45**MOT test number** 148915970873**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 December
Days left	215
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-01-28
Last registration	2024-01-10
Complete history	See info



Registration #1	2014-01-28	7 mi
Registration #2	2017-01-24	39.260 mi
Registration #3	2018-01-25	55.969 mi
Registration #4	2019-03-16	69.561 mi
Registration #5	2020-03-06	87.948 mi
Registration #6	2020-03-09	88.085 mi
Registration #7	2021-03-11	93.884 mi
Registration #8	2022-03-10	95.277 mi
Registration #9	2023-03-09	96.277 mi
Registration #10	2023-03-09	96.277 mi
Registration #11	2023-03-09	96.277 mi
Registration #12	2023-03-09	96.277 mi
Registration #13	2023-03-09	96.277 mi
Registration #14	2024-01-10	96.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1964 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4

Number of axles

2

Engine number

CAAC626219