



General information

| | |
|---------------------|-------------------|
| Make | FORD |
| Model | GALAXY ZETEC TDCI |
| Colour | Silver |
| Year of manufacture | 2008 |
| Top speed | 72 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 130 BHP |
| Max. torque | 340 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 28.3 mpg |
| Consumption extra urban | 47.9 mpg |
| Consumption combined | 38.2 mpg |
| CO2 emission | 196 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-24 |
| Pictures | 14 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-28 |
| MOT pass rate | 78 % |
| MOT passed | 14 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 6 |

MOT #18 2023-10-16 10:52

MOT test number 280428462581

Result ✓ Passed

Next expiry date 2024-10-28

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17 2022-10-24 13:47

MOT test number 390448837442

Result ✓ Passed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

Minor Front Anti-roll bar ball joint dust cover severely deteriorated both sides (5.3.4 (b) (i))

MOT #16 2021-10-29 18:31

MOT test number 788921886713

Result ✓ Passed

**MOT #15**

2021-03-25 10:56

MOT test number

712909150264

Result

✓ Passed

Advice

Front Shock absorbers light misting of oil or has limited damping effect both (5.3.2 (b))

MOT #14

2019-06-04 14:09

MOT test number

203573935696

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge both shoulders of the tyre worn (5.2.3 (e))

Advice

Items removed from driver's view prior to test

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice

Offside Rear Nail in tyre

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Central Child Seat fitted not allowing full inspection of adult belt

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect appears to have light mist (vehicle tested in wet conditions) (5.3.2 (b))

MOT #13

2018-06-08 13:31

MOT test number

825662685253

Result

✓ Passed

Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice

Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2018-06-06 10:04**MOT test number** 619237406455**Result** ✗ Failed**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #11** 2017-05-22 12:43**MOT test number** 972905129945**Result** ✓ Passed**MOT #10** 2017-05-18 10:00**MOT test number** 173329389160**Result** ✗ Failed**Fail** Parking brake lever defective so that it cannot be satisfactorily operated (3.1.3c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #9** 2016-06-10 09:28**MOT test number** 168821033798**Result** ✓ Passed**MOT #8** 2015-08-29 14:29**MOT test number** 671970583923**Result** ✓ Passed

**MOT #7** 2014-08-26 15:40**MOT test number** 628448734213**Result** ✓ Passed**MOT #6** 2013-08-23 09:28**MOT test number** 107715533228**Result** ✓ Passed**MOT #5** 2013-08-23 09:28**MOT test number** 628065333248**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**MOT #4** 2013-02-25 10:02**MOT test number** 515266153064**Result** ✓ Passed**MOT #3** 2012-08-24 16:33**MOT test number** 595157132208**Result** ✓ Passed**MOT #2** 2012-01-26 17:00**MOT test number** 697126822038**Result** ✓ Passed**MOT #1** 2012-01-24 11:38**MOT test number** 967664622015**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 October 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 November |
| Days left | | 186 |
| MOT expiry date | | 28 October 2024 |
| Full MOT history | | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2008-10-17 |
| Last registration | 2023-10-16 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-10-17 | 29 mi |
| Registration #2 | 2012-01-24 | 61.519 mi |
| Registration #3 | 2012-01-26 | 61.520 mi |
| Registration #4 | 2012-08-24 | 63.315 mi |
| Registration #5 | 2013-02-25 | 66.315 mi |
| Registration #6 | 2013-08-23 | 74.185 mi |
| Registration #7 | 2014-08-26 | 84.620 mi |
| Registration #8 | 2015-08-29 | 96.728 mi |
| Registration #9 | 2016-06-10 | 104.456 mi |
| Registration #10 | 2017-05-18 | 108.710 mi |
| Registration #11 | 2018-05-20 | 113.000 mi |
| Registration #12 | 2019-05-20 | 117.300 mi |
| Registration #13 | 2020-05-20 | 121.600 mi |
| Registration #14 | 2021-05-20 | 125.900 mi |
| Registration #15 | 2022-05-20 | 130.200 mi |
| Registration #16 | 2023-05-20 | 134.500 mi |
| Registration #17 | 2024-05-20 | 138.800 mi |
| Registration #18 | 2025-05-20 | 143.100 mi |
| Registration #19 | 2026-05-20 | 147.400 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2154 mm |
| Height | 1736 mm |
| Length | 4820 mm |
| Wheel base | 2850 mm |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |

Engine number

8R41849