



RENAULT

MWI30PA


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 3

Date	2022-09-10
Pictures	4
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 2

Date	2021-08-01
Pictures	1
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-31
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-07
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	19
Total items failed	21

MOT #14 2024-01-08 10:47

MOT test number 750047743755

Result ✓ Passed

Next expiry date 2025-01-07

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Shock absorbers has slight external damage to the casing both rear casings corroded (5.3.2 (b))

MOT #13 2022-11-08 12:23

MOT test number 266696252228

Result ✓ Passed

MOT #12 2021-08-16 13:21

MOT test number 836446253401

Result ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view Wiper scratches. (3.2 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #11**

2021-08-13 14:28

MOT test number

234403839624

Result**✗ Failed**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner and outer edges. Advise regular checks. (5.2.3 (e))

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Close to limits(3mm). Advise regular checks. (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view Wiper scratches. (3.2 (a) (i))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Close to limits(3mm). Advise regular checks. (5.2.3 (e))

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Rear Brake disc worn, but not excessively Both sides. (1.1.14 (a) (i))

MOT #10

2020-08-06 13:24

MOT test number

431885112481

Result**✓ Passed**

Advice Slight buckle in o/s front wheel rim.

**MOT #9** 2020-08-04 13:46**MOT test number** 820426863553**Result** ✗ Failed

- Fail** Front Driver's view of the road through the swept area of the windscreen materially affected by an obstruction (3.1 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Headlamp aim too high (4.1.2 (a))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 205/55/16 (5.2.3 (e))
- Advice** Slight buckle in o/s front wheel rim.

MOT #8 2019-07-23 13:30**MOT test number** 196369150033**Result** ✓ Passed**MOT #7** 2019-07-22 13:12**MOT test number** 784770600016**Result** ✗ Failed

- Fail** Nearside Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #6 2018-08-02 11:20**MOT test number** 833984320563**Result** ✓ Passed

**MOT #5** 2018-08-01 10:20**MOT test number** 915837380484**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear tyre sidewalls cracked**Fail** Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt outer (6.1.7 (g) (ii))**Advice** Nearside Front wiper blade split**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt outer (6.1.7 (g) (ii))**MOT #4** 2017-08-02 13:39**MOT test number** 561667254150**Result** ✓ Passed**MOT #3** 2017-08-02 08:58**MOT test number** 604300216046**Result** ✗ Failed**Fail** Offside Front Front position lamp(s) not working side light (1.1.A.3b)**Fail** Nearside Front Front position lamp(s) not working side light (1.1.A.3b)**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #2** 2016-08-08 08:10**MOT test number** 340809931762**Result** ✓ Passed



MOT #1	2016-08-05 09:17
MOT test number	836676621223
Result	✗ Failed
Fail	Centre Rear registration plate incorrect (6.3.1a)
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Fail	Centre Front registration plate incorrect (6.3.1a)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 January
Days left	248
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-06-28
Last registration	2024-01-08
Complete history	See info



Registration #1	2013-06-28	29 mi
Registration #2	2016-08-05	26.003 mi
Registration #3	2016-08-08	26.007 mi
Registration #4	2017-08-02	35.474 mi
Registration #5	2017-08-02	35.474 mi
Registration #6	2018-08-01	46.206 mi
Registration #7	2018-08-02	46.207 mi
Registration #8	2019-07-22	58.673 mi
Registration #9	2019-07-23	58.688 mi
Registration #10	2019-07-23	58.688 mi
Registration #11	2019-07-23	58.688 mi
Registration #12	2019-07-23	58.688 mi
Registration #13	2019-07-23	58.688 mi
Registration #14	2019-07-23	58.688 mi
Registration #15	2019-07-23	58.688 mi
Registration #16	2019-07-23	58.688 mi
Registration #17	2019-07-23	58.688 mi
Registration #18	2019-07-23	58.688 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	D126438