





General information

| Make | HYUNDAI |
|---------------------|----------------------|
| Model | TUCSON T-GDI PREMIUM |
| Colour | Blue |
| Year of manufacture | 2019 |
| Top speed | 126 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 175 BHP |
|-------------------------|---------------------|
| Max. torque | 265 Nm at 4.500 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 29.4 mpg |
| Consumption extra urban | 44.8 mpg |
| Consumption combined | 37.7 mpg |
| CO2 emission | 173 g/km |
| CO2 label | Н |







Internet history

Entry 1

Date Pictures 2022-03-31

12

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2025-03-28 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 8 |
| Total items failed | 2 |

| MOT #4 | | 2024-03-28 13:54 |
|---|----------------------------|------------------|
| MOT test r | number | 970963398419 |
| Result | | 🗸 Passed |
| Next expir | y date | 2025-03-28 |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge. (5.2.3 (e)) | | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge. (5.2.3 (e)) | | |
| Advice | Nearside Rear Nail in tyre | |

2024-03-27 08:59 MOT #3 484000765578 **MOT test number** Result **X** Failed Advice Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge. (5.2.3 (e)) Advice Nearside Rear Nail in tyre Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Advice Offside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge. (5.2.3 (e)) Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail





| MOT #2 | | 2023-03-17 09:39 |
|------------------|---|------------------|
| MOT test I | number | 709545194057 |
| Result | | ✓ Passed |
| Advice Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Auvice | onside front fyre worn close to regul initity worn on edge (3.2.5 (c)) | |

| MOT #1 | 2022-03-02 16:52 |
|-----------------|------------------|
| MOT test number | 982069820358 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | √ мот |
|-----------------------------------|---------------------------|
| Tax due: 1 October 2024 | Expires: 28 March 2025 |
| Tax status | Valid until 1 October |
| Days left | 155 |
| MOT expiry date | 28 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|--------------|
| Band | J |
| First licence fee (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | |
| Category | Lamp |
| Туре | K K K |
| Damage 2 | AMPL |
| | F Store |
| Date | 1. F |
| Category | ant |
| Туре | |

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ******** | |
| ******* | |
| ********* | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this HYUNDAI had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |







Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-03-29 |
| Last registration | 2024-03-28 |
| Complete history | See info |



| Registration #1 | 2019-03-29 | 18 mi |
|-----------------|------------|------------|
| Registration #2 | 2022-03-02 | 26.693 mi |
| Registration #3 | | 11.777 mi |
| Registration #4 | | 11.777 est |
| Registration #5 | | 11.227 mi |
| Registration #6 | | 11.117 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 2065 mm |
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Max. allowed weight | 2110 kg |
| Additional information | |
| Fuel tank capacity | 62 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 11/11 |

Engine number

G4FJJZ694605