



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Black
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 2

Date	2022-02-06
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-02-05
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	40
Total items failed	6

MOT #18	2023-11-07 07:29
MOT test number	649376263440
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #17	2023-11-02 08:39
MOT test number	921420500621
Result	✗ Failed
Minor	Central Rear Windscreen wiper blade defective Split (3.4 (b) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #16	2022-11-29 16:21
MOT test number	970292880441
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))

**MOT #15**

2022-11-29 11:28

MOT test number

883525839133

Result**✗ Failed****Minor**

Offside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2021-11-02 15:42

MOT test number

754330883050

Result**✓ Passed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Oil leaks

**MOT #13**

2020-11-05 12:25

MOT test number

574648547343

Result

✓ Passed

- Advice** Offside Front steering gator twisted
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Central Exhaust mounting defective likely to fail (6.1.2 (a))

MOT #12

2019-06-05 09:06

MOT test number

292467197467

Result

✓ Passed

- Advice** Front front exhaust flexiable joint in poor condition
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view stone chip in screen (3.2 (a) (i))
- Advice** Rear rear exhaust support hanger broken away from pipe
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #11

2018-06-01 11:05

MOT test number

592467926064

Result

✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**MOT #10** 2018-06-01 08:50**MOT test number** 776432587759**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**MOT #9** 2017-06-09 09:47**MOT test number** 459808063933**Result** ✓ Passed**MOT #8** 2016-06-14 14:55**MOT test number** 508230260413**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #7** 2016-06-14 14:55**MOT test number** 878521148150**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #6** 2015-03-12 09:39**MOT test number** 248641275070**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #5** 2014-03-07 10:29**MOT test number** 345586864043**Result** ✓ Passed**Notice** Front discs slight wear**MOT #4** 2013-02-28 09:35**MOT test number** 966289453039**Result** ✓ Passed**Notice** Long handbrake travel**Advice** Centre Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #3** 2012-03-12 13:10**MOT test number** 105832272417**Result** ✓ Passed**Notice** Stone chips in windscreen**MOT #2** 2011-06-30 14:08**MOT test number** 486661581164**Result** ✓ Passed**MOT #1** 2011-01-19 10:57**MOT test number** 688079511087**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
28 November 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FT57EJU
Plate since	2019-03-28
Current registration	FT57EJU
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-02-25
Last registration	2023-11-07
Complete history	See info



Registration #1	2008-02-25	15 mi
Registration #2	2011-01-19	24.592 mi
Registration #3	2011-06-30	26.490 mi
Registration #4	2012-03-12	31.591 mi
Registration #5	2013-02-28	44.766 mi
Registration #6	2014-03-07	52.450 mi
Registration #7	2015-03-12	61.592 mi
Registration #8	2016-06-14	74.462 mi
Registration #9	2016-06-14	74.462 mi
Registration #10	2017-06-09	82.143 mi
Registration #11	2018-06-01	92.690 mi
Registration #12	2019-06-01	101.277 mi
Registration #13	2019-06-01	101.277 mi
Registration #14	2019-06-01	101.277 mi
Registration #15	2019-06-01	101.277 mi
Registration #16	2019-06-01	101.277 mi
Registration #17	2019-06-01	101.277 mi
Registration #18	2019-06-01	101.277 mi
Registration #19	2019-06-01	101.277 mi
Registration #20	2019-06-01	101.277 mi
Registration #21	2019-06-01	101.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295