





report date: 2024-03-28

General information

Make	FORD
Model	B-MAX ZETEC
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-29


Pictures 10

Listing price <u>View report</u>











source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history	
MOT expiry date	2025-03-20
MOT pass rate	90 %
MOT passed	Q

MOT passed 9

Failed MOT tests 1

Total advice items 13

Total items failed 0

 MOT #10
 2024-03-21 11:48

 MOT test number
 540606129470

 Result
 ✓ Passed

 Next expiry date
 2025-03-20

 MOT #9
 2023-02-23 10:09

 MOT test number
 123194505079

 Result
 ✓ Passed

MOT #8 2022-02-25 13:45

MOT test number 167196133241

Result ✓ Passed

MOT #7 2022-02-18 13:40

MOT test number 287882577172

Result X Failed

MAJOR Windscreen washer not working (3.5 (a))

Advice Nearside Front head lamp mount broken but still secure

Advice Tyre pressure light on

MAJOR Offside Front Headlamp insecure (4.1.1 (c))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2021-02-15 16:36

MOT test number 835869080140

Result ✓ Passed

MOT #5 2020-02-14 12:33

MOT test number 200961509363

Result ✓ Passed

MOT #4 2019-02-18 10:35

MOT test number 316064662765

Result ✓ Passed

MOT #3 2018-02-15 15:42

MOT test number 476249370051

Result ✓ Passed

Advice Nearside Rear Tyre perished

Advice Offside Front Tyre perished

Advice Offside Front Tyre structure starting to deteriorate on inner edge of tread surface

Advice Offside Rear Tyre worn thin on inner edge of tread surface

Advice Nearside Front Tyre perished

Advice Offside Rear Tyre perished

Advice Nearside Front Tyre structure starting to deteriorate on inner edge of tread surface

Advice Nearside Rear Tyre worn thin on inner edge of tread surface

MOT #2 2017-02-16 12:49

MOT test number 717359880163

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1

MOT test number

789149873538

Result

Advice Tread cracked all tyres

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

α	vner	hi	ctc	1
\cup	viiei	ш	SIL	ע ונ

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
manage of the same		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-01-09
Last registration	2024-03-21
Complete history	See info



Registration #1	2013-01-09	28 mi
Registration #2	2015-12-01	10.404 mi
Registration #3	2017-02-16	16.413 mi
Registration #4	2018-02-15	20.696 mi
Registration #5	2019-02-18	25.947 mi
Registration #6	2020-02-14	28.889 mi
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

CT29076