



report date: 2024-03-29

General information

Make	MAZDA
Model	5 SPORT
Colour	Red
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.4 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-07-04
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-29
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	39
Total items failed	11

MOT #16	2023-09-23 10:18
MOT test number	420887207569
Result	✓ Passed
Next expiry date	2024-09-29
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2022-09-24 10:56
MOT test number	104677973329
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))

MOT #14	2021-09-30 09:17
MOT test number	108181401534
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))
Advice	Surface rust all over the car

**MOT #13**

2021-09-25 16:36

MOT test number

647872126029

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Surface rust all over the car**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MOT #12**

2020-09-03 09:51

MOT test number

310798016690

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge Both front on outer edges (5.2.3 (e))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #11**

2019-09-25 12:49

MOT test number

635122327614

Result

✓ Passed

Advice Exhaust corroded**Advice** Exhaust has a minor leak of exhaust gases middle /rear (6.1.2 (a))

**MOT #10**

2019-09-25 08:58

MOT test number

409479272048

Result**✗ Failed****Advice** Exhaust corroded**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Exhaust has a minor leak of exhaust gases middle /rear (6.1.2 (a))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #9**

2018-09-14 07:56

MOT test number

787240250287

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e))**MOT #8**

2018-09-14 07:56

MOT test number

666211254823

Result**✗ Failed****Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #7** 2017-09-14 08:11**MOT test number** 921704127340**Result** ✓ Passed

Advice Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #6 2016-09-29 10:55**MOT test number** 573927296899**Result** ✓ Passed

Advice Offside Front Upper Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear mounting (2.4.G.2)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Lower Suspension arm rubber mounting deteriorated but not resulting in excessive movement rear mounting (2.4.G.2)

Advice Both front tyres bald on inner/outer edges

Advice Nearside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #5 2015-09-15 10:34**MOT test number** 750930796248**Result** ✓ Passed**MOT #4** 2014-09-16 16:52**MOT test number** 327229754409**Result** ✓ Passed

**MOT #3**

2014-09-16 09:08

MOT test number

758669154285

Result**✗ Failed****Fail** Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2**

2013-09-23 16:46

MOT test number

577596863202

Result**✓ Passed****Notice** Nearside rear tyre devoid of tread on inner shoulder, worn outer and perish cracks in areas**Notice** Under-trays fitted obscuring some underside components**Notice** Offside rear tyre close to devolving of tread on inner edge, worn outer and perish cracking in areas**Notice** Both front tyres have edge wear**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1**

2012-09-14 09:00

MOT test number

817638252213

Result**✓ Passed****Notice** Both rear tyres worn on inner shoulders, and cracking in between tread areas**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 September 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-17
Last registration	2023-09-23
Complete history	See info



Registration #1	2009-09-17	7 mi
Registration #2	2012-09-14	31.842 mi
Registration #3	2013-09-23	41.977 mi
Registration #4	2014-09-16	52.081 mi
Registration #5	2014-09-16	52.081 mi
Registration #6	2015-09-15	63.283 mi
Registration #7	2016-09-29	74.030 mi
Registration #8	2017-09-14	83.281 mi
Registration #9	2018-09-14	94.039 mi
Registration #10	2019-09-23	105.291 mi
Registration #11	2020-09-23	116.543 mi
Registration #12	2021-09-23	127.795 mi
Registration #13	2022-09-23	139.047 mi
Registration #14	2023-09-23	150.299 mi
Registration #15	2024-03-29	161.551 mi
Registration #16	2024-03-29	172.803 mi
Registration #17	2024-03-29	184.055 mi
Registration #18	2024-03-29	195.307 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1410 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Engine number	LF 10734938