



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB SHUTTLE SE 130TDI
Colour	Blue
Year of manufacture	2006
Top speed	104 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.4 mpg
CO2 emission	227 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-07-28
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-09
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #10	2023-05-10 10:48
MOT test number	942597246934
Result	✓ Passed
Next expiry date	2024-05-09

MOT #9	2022-05-09 13:21
MOT test number	170839867586
Result	✓ Passed

MOT #8	2020-10-22 10:11
MOT test number	493661818848
Result	✓ Passed

MOT #7	2019-05-16 11:47
MOT test number	605731962760
Result	✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6** 2015-06-26 11:33**MOT test number** 809817175156**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2014-04-14 11:22**MOT test number** 279894904419**Result** ✓ Passed**Advice** Nearside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**Advice** Offside Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Gearbox mounting defective**MOT #4** 2013-08-01 09:29**MOT test number** 309933613210**Result** ✓ Passed**MOT #3** 2012-05-31 10:49**MOT test number** 216312052158**Result** ✓ Passed**MOT #2** 2011-05-31 09:25**MOT test number** 696171251185**Result** ✓ Passed



MOT #1	2009-09-02 10:05
MOT test number	571885449289
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	EF06YTP
Plate since	2019-06-29
Current registration	EF06YTP
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2006-06-29
Last registration	2023-05-10
Complete history	See info



Registration #1	2006-06-29	7 mi
Registration #2	2009-09-02	31.099 mi
Registration #3	2011-05-31	39.009 mi
Registration #4	2012-05-31	45.194 mi
Registration #5	2013-08-01	49.666 mi
Registration #6	2014-04-14	51.232 mi
Registration #7	2015-05-29	51.232 mi
Registration #8	2016-05-29	51.232 mi
Registration #9	2017-05-29	51.232 mi
Registration #10	2018-05-29	51.232 mi
Registration #11	2019-05-29	51.232 mi
Registration #12	2020-05-29	51.232 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1904 mm
Height	1969 mm
Length	4890 mm
Kerb weight	2197 kg
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	9
Number of axles	2
Engine number	BNZ 024265