





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	207 VERVE
Colour	Red
Year of manufacture	2009
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

#### Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

#### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

### MOT history

MOT expiry date	2024-12-04
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #15		2023-12-05 10:39
MOT test	number	662638908404
Result		<b>✓</b> Passed
Next expiry date 2024-12-04		2024-12-04
Advice Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))		
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edges + 2mm at	centre (5.2.3 (e))

MOT #14	2023-12-04 09:37	
MOT test number	294283012050	
Result	<b>X</b> Failed	
Advice Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))		
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge edges + 2mm at centre (5.2.3 (e))		
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))		

MOT #13	2022-11-07 18:14
MOT test number	370686332893
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12		2022-02-01 10:22
MOT test nur	nber	174072940208
Result		✓ Passed
Advice Ex	chaust has a minor leak of exhaust gases front pipe (6.1.2 (a))	

MOT #11		2021-02-03 16:41
MOT test	number	569826336602
Result		<b>✓</b> Passed
MOT #10		2020-06-10 09:26
MOT test	number	377462572601
Result		✓ Passed
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))	

MOT #9		2019-04-25 08:18
MOT test	number	627976926088
Result		✓ Passed
Advice Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))  Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #8		2018-05-02 09:24
MOT test	number	838975899749
Result		✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2018-05-02 07:55

**MOT test number** 704591919128

**Result** X Failed

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #6** 2017-05-02 16:00

MOT test number 112625648001

**Result** 
✓ Passed

MOT #5 2016-05-05 09:08

**MOT test number** 735989298730

**Result** ✓ Passed

**MOT #4** 2015-07-06 12:34

**MOT test number** 445897585177

**Notice** Oil leak

MOT #3 2014-06-30 12:59

**MOT test number** 919911184117

Result \rightarrow Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Nearside front tyre wearing on outer edge

MOT #2 2013-06-27 10:24

**MOT test number** 566118273160

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

 MOT #1
 2012-06-29 13:44

 MOT test number
 789631982168

**Result** ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	4 December 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

$\sim$		h:at	
- CJV	vner	misi	or

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		IGEOT
********		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		9
Current registration	NK SILE	
Plate since		
Current registration	OK SIE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-30
Last registration	2023-12-05
Complete history	See info



Registration #1	2009-06-30	27 mi
Registration #2	2012-06-29	14.193 mi
Registration #3	2013-06-27	18.603 mi
Registration #4	2014-06-30	23.293 mi
Registration #5	2015-07-06	28.214 mi
Registration #6	2016-05-05	32.772 mi
Registration #7	2017-05-02	39.263 mi
Registration #8	2018-05-02	46.900 mi
Registration #9	2018-05-02	46.900 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.79 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1213 kg
Max. allowed weight	1580 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

**Engine number** FST36005359