



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Grey
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





## MOT history

MOT expiry date	2024-10-27
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	30
Total items failed	0

MOT #15 2023-10-24 10:55

MOT test number 500052790303

Result ✓ Passed

Next expiry date 2024-10-27

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14 2022-10-26 11:23

MOT test number 384633956894

Result ✓ Passed

- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive inner sill (5.3.6 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-10-25 10:33**MOT test number** 128950819496**Result** ✓ Passed**Advice** Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Minor** Rear Position lamp with a multiple light source up to 1/2 not functioning n/s.o/s (4.2.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-10-16 15:20**MOT test number** 680007364165**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing inside tread (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm in centre of tread and worn on outside of tyre (5.2.3 (e))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn axle bush cracked /perished, but still secure (5.1.2 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing inside tread (5.2.3 (d) (ii))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn rear axle bush cracked/perished, but still secure (5.1.2 (b) (i))**MOT #11** 2019-04-26 10:56**MOT test number** 518556866420**Result** ✓ Passed**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2019-04-25 13:27

**MOT test number**

475350368548

**Result****✗ Failed****DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt split boot (5.3.4 (b) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MAJOR** Nearside Front Brake hose excessively damaged (1.1.12 (b) (ii))**MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9**

2018-04-26 11:39

**MOT test number**

548654260387

**Result****✓ Passed****Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8**

2017-04-07 14:01

**MOT test number**

493255951212

**Result****✓ Passed****MOT #7**

2016-04-15 15:36

**MOT test number**

774537768800

**Result****✓ Passed****MOT #6**

2015-04-25 09:52

**MOT test number**

755895315103

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-03-28 09:35**MOT test number** 569267584088**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-04-26 17:22**MOT test number** 258376913156**Result** ✓ Passed**MOT #3** 2012-04-20 17:54**MOT test number** 917881712134**Result** ✓ Passed**MOT #2** 2011-04-13 12:06**MOT test number** 978783701150**Result** ✓ Passed**MOT #1** 2010-04-28 12:05**MOT test number** 223608310492**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
27 October 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	27 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	KH07GYR
Plate since	2019-03-29
Current registration	KH07GYR
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-04-27
Last registration	2023-10-24
Complete history	<a href="#">See info</a>



Registration #1	2007-04-27	8 mi
Registration #2	2010-04-28	22.829 mi
Registration #3	2011-04-13	30.882 mi
Registration #4	2012-04-20	38.173 mi
Registration #5	2013-04-26	44.264 mi
Registration #6	2014-03-28	50.745 mi
Registration #7	2015-04-25	58.978 mi
Registration #8	2016-04-15	61.378 mi
Registration #9	2016-05-20	61.378 mi
Registration #10	2016-05-20	61.378 mi
Registration #11	2016-05-20	61.378 mi
Registration #12	2016-05-20	61.378 mi
Registration #13	2016-05-20	61.378 mi
Registration #14	2016-05-20	61.378 mi
Registration #15	2016-05-20	61.378 mi
Registration #16	2016-05-20	61.378 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZU948780