



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SPORT TDI (130BHP)
Colour	Silver
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	420 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	51.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-13
Pictures	39
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #17	2020-12-23 13:51
MOT test number	628657619778
Result	✓ Passed
Next expiry date	2021-12-22

MOT #16	2020-12-21 16:12
MOT test number	533230782407
Result	✗ Failed

- Fail** Nearside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #15	2019-12-17 11:28
MOT test number	500504168221
Result	✓ Passed

- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14	2018-12-19 12:30
MOT test number	432809274379
Result	✓ Passed

- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2017-12-18 14:44

MOT test number

325247739653

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Oil leak
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Rear Nail in tyre
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #12

2016-12-21 18:06

MOT test number

225256594699

Result

✓ Passed

- Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Oil leak
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #11	2015-07-02 14:16
MOT test number	278293885125
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #10	2014-07-03 14:39
MOT test number	236694684141
Result	✓ Passed

MOT #9	2013-07-01 15:36
MOT test number	797032483119
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2013-06-28 16:40
MOT test number	606589073152
Result	✗ Failed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Advice	Nearside Front constant velocity joint is slightly worn (2.5.C.1b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Advice	Offside Front constant velocity joint is slightly worn (2.5.C.1b)

**MOT #7** 2012-07-03 09:53**MOT test number** 869925182149**Result** ✓ Passed**MOT #6** 2012-07-03 09:53**MOT test number** 676955182160**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2011-07-02 11:04**MOT test number** 838083581123**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2010-06-24 10:02**MOT test number** 281575470122**Result** ✓ Passed**MOT #3** 2009-06-10 14:01**MOT test number** 970801169131**Result** ✓ Passed**MOT #2** 2008-06-20 10:18**MOT test number** 941922078174**Result** ✓ Passed**MOT #1** 2007-06-29 16:48**MOT test number** 793280487174**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-03-19
Last registration	2020-12-23
Complete history	See info



Registration #1	2004-03-19	25 mi
Registration #2	2007-06-29	76.258 mi
Registration #3	2008-06-20	79.667 mi
Registration #4	2009-06-10	82.830 mi
Registration #5	2010-06-24	86.799 mi
Registration #6	2011-07-02	89.859 mi
Registration #7	2012-07-03	13.928 mi
Registration #8	2013-06-28	99.439 mi
Registration #9	2013-07-01	99.465 mi
Registration #10	2014-06-29	101.377 mi
Registration #11	2015-06-29	101.377 mi
Registration #12	2016-06-29	101.377 mi
Registration #13	2017-06-29	101.377 mi
Registration #14	2018-06-29	101.377 mi
Registration #15	2019-06-29	101.377 mi
Registration #16	2020-06-29	101.377 mi
Registration #17	2021-06-29	101.377 mi
Registration #18	2022-06-29	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2018 mm
Height	1446 mm
Length	4376 mm
Wheel base	2519 mm
Kerb weight	1440 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2

Engine number

ASZ440165