



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 625 LX L1 HDI
Colour	Silver
Year of manufacture	2008
Top speed	99 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-02-28
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	31
Total items failed	16

MOT #17	2024-03-01 15:31
MOT test number	163330802042
Result	✓ Passed
Next expiry date	2025-02-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #16**

2024-02-20 09:20

MOT test number

397258567271

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Headlamp aim unable to be tested (4.1.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm outer edge (5.2.3 (e))

MOT #15

2023-02-03 08:44

MOT test number

953356686261

Result**✓ Passed**

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14

2022-01-08 18:01

MOT test number

333538925003

Result**✓ Passed**

- Advice** Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-01-12 15:16**MOT test number** 665228426243**Result** ✓ Passed**MOT #12** 2019-09-11 15:02**MOT test number** 656314948901**Result** ✓ Passed**MOT #11** 2019-09-11 08:34**MOT test number** 780719065085**Result** ✗ Failed**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #10** 2018-09-14 10:33**MOT test number** 158741596664**Result** ✓ Passed**Advice** Spare tyre defective**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-09-01 12:53**MOT test number** 747412296345**Result** ✓ Passed

**MOT #8** 2017-09-01 12:53**MOT test number** 454837696215**Result** ✗ Failed**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #7** 2016-07-15 15:59**MOT test number** 879582825422**Result** ✓ Passed**MOT #6** 2016-07-15 12:44**MOT test number** 427567236978**Result** ✗ Failed**Fail** Nearside Obligatory mirror missing (8.1.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2015-06-03 10:52**MOT test number** 748024055122**Result** ✓ Passed**Notice** Nearside rear tyre low**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre scrubbed on edge**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4**

2015-06-02 16:44

MOT test number

647583755109

Result**✗ Failed**

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Centre Seat belt retracting mechanism defective (5.2.5b)
- Notice** Nearside rear tyre low
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** High level brake light not working
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Notice** Nearside front tyre scrubbed on edge
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3

2013-10-10 16:18

MOT test number

896863883274

Result**✓ Passed****MOT #2**

2012-09-24 10:24

MOT test number

465858362250

Result**✓ Passed****MOT #1**

2011-09-27 10:29

MOT test number

125140071229

Result**✓ Passed**

- Notice** Oil leak onto cat



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
28 February 2025

Tax status		Valid until 1 October
Days left		156
MOT expiry date		28 February 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-08-21
Last registration	2024-03-01
Complete history	See info



Registration #1	2008-08-21	17 mi
Registration #2	2011-09-27	15.760 mi
Registration #3	2012-09-24	25.451 mi
Registration #4	2013-10-10	37.289 mi
Registration #5	2015-06-02	51.551 mi
Registration #6	2015-06-03	51.551 mi
Registration #7	2016-07-15	55.907 mi
Registration #8	2016-07-15	55.907 mi
Registration #9	2017-09-01	68.214 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	2112 mm
Height	1834 mm
Length	4380 mm
Kerb weight	1354 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBAC0011233