





report date: 2024-03-29

General information

Make	RENAULT
Model	LAGUNA TOMTOM EDITION DCI FAP ECO2
Colour	Black
Year of manufacture	2009
Top speed	130 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



MOT history

MOT expiry date	2021-09-02
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	15
Total items failed	7

MOT #13	2020-09-03 15:09
MOT test number	710911339293
Result	✓ Passed
Next expiry date	2021-09-02
Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1	(b))

MOT #12	2020-09-02 11:01
MOT test number	186964672111
Result	X Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))
Fail Nearside Side repeater missing (4.4.1 (a) (ii))	

MOT #11	2019-07-17 12:29
MOT test number	321724888245
Result	✓ Passed
MOT #10	2018-07-20 09:40
MOT test number	959543964750
Result	✓ Passed

CarCheck.co.uk page 2/12



LY09FKD

report date: 2024-03-29

MOT #9	2017-08-03 09:46
MOT test number	923941344630
Result	✓ Passed
Advice Front under tray fitted	

MOT #8		2016-07-27 09:55
MOT test	number	334551300479
Result		✓ Passed
MOT #7		2015-07-24 14:42
MOT test	number	169315905289
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Under-trays fitted obscuring some underside components	

MOT #6		2015-07-22 10:13
MOT test	number	845223705291
Result		X Failed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Notice	Under-trays fitted obscuring some underside components	
Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)		
Fail O	ffside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2))

CarCheck.co.uk page 3/12



MOT #5 2015-07-03 14:52

MOT test number 638164985194

Result X Failed

Fail Offside Rear Passenger's seat cannot be secured in the upright position. (6.2.A.2)

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Under-trays fitted obscuring some underside components

MOT #4 2014-07-04 12:42

MOT test number 539985984187

Result ✓ Passed

MOT #3 2013-07-03 11:29

MOT test number 279394983174

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Nail in nearside rear tyre

MOT #2 2012-09-14 16:14

MOT test number 875228852265

Result ✓ Passed

Notice Both fornt tyres has small cuts on outer wall.

CarCheck.co.uk page 4/12



MOT #1 2012-09-14 16:14

MOT test number 505268552264

Result

× Failed

Pass with rectification

Front Windscreen washer provides insufficient washer liquid (8.2.3)

Notice

Both fornt tyres has small cuts on outer wall.

CarCheck.co.uk page 5/12





Tax & MOT check



Tax expired:
11 January 2021

X MOT

Expired: 2 September 2021

Tax status	Expired at 11 January 2021
Days left	1205 days too late
MOT expiry date	2 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when motorly	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	NE ZIN
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-07-27
Last registration	2020-09-03
Complete history	See info



Registration #1	2009-07-27	25 mi
Registration #2	2012-09-14	17.232 mi
Registration #3	2013-07-03	19.812 mi
Registration #4	2014-07-04	24.013 mi
Registration #5	2015-07-03	27.313 mi
Registration #6	2015-07-22	27.631 mi
Registration #7	2015-07-24	27.631 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.177 mi
Registration #12		11.177 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4801 mm
Wheel base	2758 mm
Kerb weight	1483 kg
Max. allowed weight	2051 kg

Additional information

Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine numberC001380