




report date: 2024-03-28

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Grey
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	379 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-12-09
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	34
Total items failed	6

MOT #15	2023-12-16 10:25
MOT test number	304322670797
Result	✓ Passed
Next expiry date	2024-12-19
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2022-11-26 12:22
MOT test number	161617463674
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2021-12-20 09:46**MOT test number** 937344688347**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-11-23 16:07**MOT test number** 242398832571**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has negligible damping effect (5.3.2 (d))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-12-02 10:56**MOT test number** 426697988364**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #10** 2019-11-26 11:07**MOT test number** 258290923677**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn to outer tread (5.2.3 (e))**MOT #9** 2018-12-10 17:46**MOT test number** 995721125825**Result** ✓ Passed

**MOT #8** 2017-07-08 09:22**MOT test number** 415575538618**Result** ✓ Passed

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #7 2017-07-08 09:22**MOT test number** 338185889845**Result** ✗ Failed

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #6 2016-06-11 08:44**MOT test number** 660470288106**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2015-07-09 13:35**MOT test number** 326870395184**Result** ✓ Passed

**MOT #4**

2015-07-08 15:17

MOT test number

668319285101

Result**✗ Failed**

- Fail** Offside Headlamp cleaning device inoperative (1.7.2)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside Headlamp cleaning device inoperative (1.7.2)
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #3

2014-08-19 12:05

MOT test number

499111634246

Result**✓ Passed**

- Notice** Both front tyres wearing on outer edges and perishing/splitting through base of tread
- Notice** Under-trays fitted obscuring some underside components
- Notice** Offside rear tyre perishing
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #2

2013-08-23 16:53

MOT test number

186005933214

Result**✓ Passed**

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components



MOT #1	2012-08-31 16:15
MOT test number	967694642227
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Notice	Sill covers fitted



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
19 December 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XX XX XX
Plate since	2019-01-01
Current registration	XX XX XX
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-31
Last registration	2023-12-16
Complete history	See info



Registration #1	2009-03-31	10 mi
Registration #2	2012-08-31	24.700 mi
Registration #3	2013-08-23	28.256 mi
Registration #4	2014-08-19	33.457 mi
Registration #5	2015-07-08	36.400 mi
Registration #6	2015-07-09	36.400 mi
Registration #7	2016-06-11	41.860 mi
Registration #8	2017-07-08	50.116 mi
Registration #9	2017-07-08	50.116 mi
Registration #10	2018-06-20	55.277 mi
Registration #11	2018-06-20	55.277 mi
Registration #12	2018-06-20	55.277 mi
Registration #13	2018-06-20	55.277 mi
Registration #14	2018-06-20	55.277 mi
Registration #15	2018-06-20	55.277 mi
Registration #16	2018-06-20	55.277 mi
Registration #17	2018-06-20	55.277 mi

More info >



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1750 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ694008020