





report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO V220 CDI AMBIENTE
Colour	Blue
Year of manufacture	2000
Top speed	102 mph
0 - 60 mph	17.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	300 Nm at 1.800 rpm
Engine capacity	2.151 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/16



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-14

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-14
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	60
Total items failed	6

MOT #21		2023-11-15 09:48
MOT test	number	952863155150
Result		✓ Passed
Next expi	ry date	2024-11-14
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice Integral body structure is corroded but structural rigidity is not significantly reduced both sides front jacking points rusty (6.1.1 (c) (i))		
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Under body rusty	
Advice	Nearside Front Brake pipe corroded, covered in grease or other materia	l (1.1.11 (c))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))

CarCheck.co.uk page 3/16



report date: 2024-03-29

MOT #20 2023-11-02 13:27

MOT test number 702717485852

Result X Failed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Fuel cap/sealing device ineffective locked (6.1.3 (b) (i))

MAJOR Offside Front Brake prescribed area is excessively corroded inner wheel arch area nr to brake pipe holed (1.1.21 (e) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Integral body structure is corroded but structural rigidity is not significantly reduced both sides front jacking points rusty (6.1.1 (c) (i))

Advice Eletrical fumes in cab

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength under sill nr to trail arm mounting area (5.3.6 (a) (i))

MAJOR Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MAJOR Offside Front Brake pipe excessively corroded (1.1.11 (c))

MAJOR Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt both sides (6.1.7 (g) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MAJOR Rear Seat belt missing both rear buckles not present (7.1.2 (a))

Advice Under body rusty

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT #19 2022-10-26 09:07

MOT test number 634868410002

Result X Failed

MAJOR Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (front & rear) (7.1.1 (a) (i))

MAJOR Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill under vehicle (5.3.6 (a) (i))

MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

MAJOR Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced sill under vehicle (7.1.1 (a) (i))

MAJOR Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #18 2021-08-19 11:48

MOT test number 493256231289

Result ✓ Passed

Advice Coil spring corroded all (5.3.1 (b) (i))

Advice Front metal brake pipes slightly corroded

Advice Front chassis rails forming corrosion

MOT #17 2021-08-19 11:48

MOT test number 594915370799

Result X Failed

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front metal brake pipes slightly corroded

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Coil spring corroded all (5.3.1 (b) (i))

Advice Front chassis rails forming corrosion

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #16 2020-11-17 10:40

MOT test number 233044229856

Advice Nearside Front Outer Seat belt anchorage prescribed area is corroded but not considered excessive corrosion starting on outer side sill (7.1.1 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Inner Seat belt anchorage prescribed area is corroded but not considered excessive corrosion starting on inner side sill (7.1.1 (a) (i))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive corrosion starting on inner side sill (5.3.6 (a) (i))

MOT #15 2019-09-14 14:26

MOT test number 421268853003

Result \rightarrow Passed

MOT #14 2018-09-25 10:15

MOT test number 586175465634

Result

Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13 2017-09-26 11:04

MOT test number 264171474934

Result

Passed

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT #12

MOT test number

965782315907

Result

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #11

MOT test number 608921805234

Result ✓ Passed

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

Notice Offside front tyre cracking

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Offside rear tyre cracking

MOT #10 2015-07-11 10:07 **MOT** test number 628482895150 Result × Failed Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2) **Notice** Offside front tyre cracking Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Notice** Offside rear tyre cracking Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT test number

Result

Advice (2.5.C.1a)

Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Centre Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #8

MOT test number

Fesult

Notice 2x front tyres wearing on inner edges

Notice Rear exhaust silencer deteriorating

MOT #7

MOT test number

938557172146

Result

MOT #6

MOT test number

688006521112

Result

Notice N/s/f wiper blade is slightly worn,still provides a clear view to front.

 MOT #5
 2010-04-23 12:03

 MOT test number
 202213610182

 Result
 ✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-29

MOT #4	2010-04-20 17:09
MOT test number	953220710139
Result	X Failed
Fail Offside Front Brake hose excessively deteriorated (3.6.B.4d)	
Fail Nearside Front Brake hose excessively deteriorated (3.6.B.4d)	

MOT #3	2008-10-23 10:52
MOT test number	981127498205
Result	✓ Passed
Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)	

MOT #2	2007-10-13 11:29
MOT test number	254906987271
Result	✓ Passed
MOT #1	2006-04-28 09:38
MOT test number	394798016128
Result	✓ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-29

Tax & MOT check





Expires: 14 November 2024

Tax status Expired at 1 August 2022

Days left 637 days too late

MOT expiry date 14 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 10/16



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-29

Owner	hictory
Owner	nistory

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	SIF UK
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2000-06-15
Last registration	2023-11-15
Complete history	See info



Registration #1	2000-06-15	10 mi
Registration #2	2006-04-28	14.812 mi
Registration #3	2007-10-13	19.996 mi
Registration #4	2008-10-23	31.314 mi
Registration #5	2010-04-20	33.770 mi
Registration #6	2010-04-23	33.770 mi
Registration #7	2011-05-06	35.974 mi
Registration #8	2012-06-25	38.149 mi
Registration #9	2013-05-31	39.043 mi
Registration #10	2014-06-16	43.226 mi
Registration #11	2015-07-11	50.122 mi
Registration #12	2015-07-20	50.169 mi
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		10 TFF 44

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-29

г.		_		
llim	ensior	יכ אי	WAIC	1nt
		IS CX	WEIL	41 I C

Width	1880 mm
Height	1844 mm
Length	4660 mm
Wheel base	3000 mm
Kerb weight	2011 kg

Additional information

Fuel tank capacity	78
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	61198050190383

CarCheck.co.uk page 16/16