



AV06YAF


report date: 2024-03-28

General information

Make	VOLVO
Model	V50 E4 D S V50
Colour	Red
Year of manufacture	2006
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-23
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #17	2023-06-22 12:52
MOT test number	357224667118
Result	✓ Passed
Next expiry date	2024-06-22

MOT #16	2023-06-22 12:51
MOT test number	224354627809
Result	✗ Failed
MAJOR Battery insecure and likely to cause a short circuit (4.13 (a) (ii))	

MOT #15	2022-06-09 13:25
MOT test number	270660445499
Result	✓ Passed
Advice	Offside Front Suspension component pin or bush slightly worn WHISHBONE BUSH (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Tyre slightly damaged INNER EDGE WEAR (5.2.3 (d) (ii))
Advice	Nearside Front Suspension component pin or bush slightly worn WHISHBONE BUSH (5.3.4 (a) (i))
Advice	Nearside Front Tyre slightly damaged INNER EDGE WEAR (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged INNER EDGE WEAR (5.2.3 (d) (ii))

**MOT #14** 2021-06-08 11:57**MOT test number** 671938037761**Result** ✓ Passed**MOT #13** 2020-05-28 15:15**MOT test number** 915386622996**Result** ✓ Passed**MOT #12** 2019-05-28 09:56**MOT test number** 645118642120**Result** ✓ Passed**MOT #11** 2018-06-12 16:44**MOT test number** 817096366558**Result** ✓ Passed**Advice** Both front lower arm rear bushes worn**Advice** Osr tyre perished**MOT #10** 2017-06-23 12:29**MOT test number** 694603226053**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2016-06-13 14:25**MOT test number** 507441987878**Result** ✓ Passed**Advice** Slight cracking to O/S/R TYRE SIDEWALL

**MOT #8** 2015-06-16 11:22**MOT test number** 437517065141**Result** ✓ Passed**Notice** O/s/r tyre showing signs of age (cracking)**MOT #7** 2014-06-10 16:22**MOT test number** 756711864166**Result** ✓ Passed**MOT #6** 2013-06-12 10:21**MOT test number** 147773363182**Result** ✓ Passed**MOT #5** 2012-06-11 14:50**MOT test number** 347393562116**Result** ✓ Passed**MOT #4** 2011-06-10 12:54**MOT test number** 635981361143**Result** ✓ Passed**Notice** Offside front tyre worn on inner edge**MOT #3** 2010-06-09 16:50**MOT test number** 934340360147**Result** ✓ Passed**MOT #2** 2010-06-09 15:50**MOT test number** 821120560119**Result** ✗ Failed**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)



MOT #1	2009-06-10 14:09
MOT test number	402881469187
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
22 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	22 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-06-13
Last registration	2023-06-22
Complete history	See info



Registration #1	2006-06-13	28 mi
Registration #2	2009-06-10	8.567 mi
Registration #3	2010-06-09	10.027 mi
Registration #4	2010-06-09	10.027 mi
Registration #5	2011-06-10	11.389 mi
Registration #6	2012-06-11	12.070 mi
Registration #7	2013-06-12	12.509 mi
Registration #8	2014-06-10	13.035 mi
Registration #9	2015-06-16	13.497 mi
Registration #10	2016-06-13	13.799 mi
Registration #11	2016-06-13	13.799 mi
Registration #12	2016-06-13	13.799 mi
Registration #13	2016-06-13	13.799 mi
Registration #14	2016-06-13	13.799 mi
Registration #15	2016-06-13	13.799 mi
Registration #16	2016-06-13	13.799 mi
Registration #17	2016-06-13	13.799 mi
Registration #18	2016-06-13	13.799 mi
Registration #19	2016-06-13	13.799 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1456 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4005794