



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C180K AVANTGARDE SE
Colour	Silver
Year of manufacture	2005
Top speed	137 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	220 Nm at 2.500 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	33.6 mpg
CO2 emission	203 g/km
CO2 label	K





MOT history

MOT expiry date	2024-03-20
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	47
Total items failed	6

MOT #17	2023-03-21 14:07
MOT test number	502894245258
Result	✓ Passed
Next expiry date	2024-03-20

MOT #16	2022-03-21 15:10
MOT test number	515796798553
Result	✓ Passed

MOT #15	2021-03-17 14:10
MOT test number	871305247661
Result	✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** General corrosion rear under body suspension,
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Under body boarded front to rear
- Advice** Nearside Non obligatory mirror damaged door

**MOT #14**

2020-02-22 14:47

MOT test number

631994408268

Result

✓ Passed

- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13

2019-02-23 13:32

MOT test number

427979754129

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #12

2018-02-23 10:19

MOT test number

998543835484

Result

✓ Passed

- Advice** Anti-roll bar linkage corroded but not seriously weakened rear (2.4.G.1)
- Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Coil spring corroded both front (2.4.C.1b)

MOT #11

2017-02-23 15:59

MOT test number

230171501426

Result

✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)

**MOT #10**

2016-02-25 16:28

MOT test number

335900374082

Result

✓ Passed

- Advice** Nearside Front brake discs surface pitted
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Under tray cover fitted
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Offside Front brake discs surface pitted
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)

MOT #9

2016-02-25 16:28

MOT test number

988479040067

Result

✗ Failed

- Pass with rectification** Nearside Front Headlamp aim too high (1.8)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front brake discs surface pitted
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Pass with rectification** Offside Front Headlamp aim too high (1.8)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Under tray cover fitted
- Advice** Offside Front brake discs surface pitted
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2014-09-09 11:42**MOT test number** 616362254283**Result** ✓ Passed**Notice** Front anti-roll bar slightly corroded, o/s/f spring slightly corroded, rear drive shaft slightly corroded**Notice** Both rear indicators slightly discoloured, front siscs worn, scored or pitted, middle exhaust box corroded, front and rear underbody has surface rust, o/s/f wheel bearing has slight play**MOT #7** 2013-09-05 11:32**MOT test number** 349398743222**Result** ✓ Passed**Advice** Nearside Front coil spring worn (2.4.C.1b)**MOT #6** 2012-09-07 15:54**MOT test number** 688541252294**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #5** 2011-09-12 11:42**MOT test number** 326815451247**Result** ✓ Passed**MOT #4** 2010-11-03 14:25**MOT test number** 974687000331**Result** ✓ Passed

**MOT #3** 2010-11-02 09:45**MOT test number** 764496500337**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front coil spring incomplete (2.4.C.1a)**MOT #2** 2009-08-08 09:41**MOT test number** 552330029269**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2008-08-01 10:32**MOT test number** 140394418204**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
6 March 2024

X

MOT

Expired:
20 March 2024

Tax status	Expired at 6 March 2024
Days left	55 days too late
MOT expiry date	20 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-08-09
Last registration	2023-03-21
Complete history	See info



Registration #1	2005-08-09	23 mi
Registration #2	2008-08-01	46.581 mi
Registration #3	2009-08-08	66.515 mi
Registration #4	2010-11-02	86.646 mi
Registration #5	2010-11-03	86.684 mi
Registration #6	2011-09-12	99.110 mi
Registration #7	2012-09-07	107.099 mi
Registration #8	2013-09-05	113.439 mi
Registration #9	2014-09-09	117.402 mi
Registration #10	2015-09-09	121.377 mi
Registration #11	2016-09-09	125.352 mi
Registration #12	2017-09-09	129.327 mi
Registration #13	2018-09-09	133.302 mi
Registration #14	2019-09-09	137.277 mi
Registration #15	2020-09-09	141.252 mi
Registration #16	2021-09-09	145.227 mi
Registration #17	2022-09-09	149.202 mi
Registration #18	2023-03-21	153.177 mi

More info >



Dimensions & weight

Width	1977 mm
Height	1426 mm
Length	4526 mm
Wheel base	2715 mm
Kerb weight	1455 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	27194630517897