



RENAULT

 **SJ6IUYF**

report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO BIZU
Colour	Silver
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	107 Nm at 4.250 rpm
Engine capacity	1.149 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-06-28
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	16
Total items failed	18

MOT #14	2023-06-15 08:29
MOT test number	960631807877
Result	✓ Passed
Next expiry date	2024-06-28
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2023-06-15 06:48
MOT test number	657511729195
Result	✗ Failed
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

MOT #12	2022-06-15 13:17
MOT test number	986237436466
Result	✓ Passed

MOT #11	2021-06-29 09:51
MOT test number	946373641665
Result	✓ Passed

**MOT #10**

2021-06-29 07:45

**MOT test number**

981078683835

**Result****✗ Failed****Fail** Front Windscreen wiper not working (3.4 (a))**MOT #9**

2020-08-11 10:17

**MOT test number**

300041698186

**Result****✗ Failed****Fail** Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Subframe (5.3.6 (a) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Subframe (5.3.6 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #8**

2019-04-09 16:43

**MOT test number**

156535291948

**Result****✓ Passed****MOT #7**

2019-04-09 10:23

**MOT test number**

306670464651

**Result****✗ Failed****Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6** 2018-04-09 08:20**MOT test number** 275721435251**Result** ✓ Passed

- Advice** Nearside Front bumper damaged
- Advice** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)

**MOT #5** 2018-04-04 08:19**MOT test number** 331747852527**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit edge (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Front bumper damaged
- Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Nearside Front Tyre worn close to the legal limit edge (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #4** 2017-03-24 11:26**MOT test number** 171835921304**Result** ✓ Passed

- Advice** Front brake discs corroded/pads low
- Advice** Rear tyre sidewalls perished



<b>MOT #3</b>	2016-03-22 14:56
---------------	------------------

<b>MOT test number</b>	230917453077
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

- Advice** Rear tyres cracking/perished
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front brake discs worn
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #2</b>	2015-03-20 16:19
---------------	------------------

<b>MOT test number</b>	315409575049
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2014-03-24 12:23
---------------	------------------

<b>MOT test number</b>	129623584420
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
28 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	28 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>REDACTED</b>
Plate since	2024-03-28
Current registration	<b>REDACTED</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-09
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2011-09-09	14 mi
Registration #2	2014-03-24	10.772 mi
Registration #3	2015-03-20	22.693 mi
Registration #4	2016-03-22	34.403 mi
Registration #5	2017-03-24	46.769 mi
Registration #6	2018-04-04	57.510 mi
Registration #7	2018-04-09	57.510 mi
Registration #8	2019-04-09	68.583 mi
Registration #9	2020-06-20	75.277 mi
Registration #10	2021-06-20	75.277 mi
Registration #11	2022-06-20	75.277 mi
Registration #12	2023-06-15	75.277 mi
Registration #13	2023-06-15	75.277 mi
Registration #14	2023-06-15	75.277 mi
Registration #15	2023-06-15	75.277 mi
Registration #16	2023-06-15	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1720 mm
Height	1497 mm
Length	4032 mm
Wheel base	2472 mm
Kerb weight	1090 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	F681487