



**RE59XEY**

report date: 2024-03-28

General information

Make	AUDI
Model	A3 TFSI S LINE SPECIAL EDITION
Colour	Black
Year of manufacture	2009
Top speed	144 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	280 Nm at 1.800 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.2 mpg
CO2 emission	169 g/km
CO2 label	H





MOT history

MOT expiry date	2025-01-17
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	56
Total items failed	7

MOT #18	2024-01-18 16:26
MOT test number	721088040570
Result	✓ Passed
Next expiry date	2025-01-17
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17	2024-01-18 14:02
MOT test number	812253675717
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Advice	Nearside Rear Nail in tyre
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge on legal limit (5.2.3 (e))



<b>MOT #16</b>	2023-01-12 14:38
<b>MOT test number</b>	480745988214
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear wheel rim buckled

<b>MOT #15</b>	2023-01-10 12:40
<b>MOT test number</b>	473706943630
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front wheel rim buckled
<b>DANGEROUS</b>	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
<b>DANGEROUS</b>	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
<b>DANGEROUS</b>	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

<b>MOT #14</b>	2021-11-29 16:03
<b>MOT test number</b>	377196165184
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

<b>MOT #13</b>	2020-11-06 15:46
<b>MOT test number</b>	614025704641
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2019-11-11 10:09
<b>MOT test number</b>	394497767840
<b>Result</b>	✓ Passed

**MOT #11**

2018-11-08 16:28

**MOT test number**

215034929735

**Result**

✓ Passed

- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10**

2018-10-24 15:58

**MOT test number**

157460093876

**Result**

✗ Failed

- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both not working (4.7.1 (b) (ii))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #9** 2017-10-12 13:13**MOT test number** 797069810265**Result** ✓ Passed**MOT #8** 2016-10-10 11:17**MOT test number** 688316742564**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Under-trays fitted obscuring some underside components**MOT #7** 2016-10-10 11:17**MOT test number** 512029759921**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Offside Rear Nail in tyre**Advice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2015-10-13 13:07**MOT test number** 534608227096**Result** ✓ Passed**Advice** Plastic under trays fitted obscuring underside components**Advice** Items removed from view prior to test

**MOT #5** 2015-10-09 11:54**MOT test number** 987186353499**Result** ✗ Failed

**Fail** Front registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

**Advice** Plastic under trays fitted obscuring underside components

**Pass with rectification** Nearside Front Headlamp aim too high (1.8)

**Fail** Offside Rear Rear position lamp(s) not working side light (1.1.A.3b)

**Advice** Items removed from view prior to test

**Fail** Rear registration plate has a feature which changes the appearance or legibility of the characters (6.3.4c)

**Pass with rectification** Offside Front Headlamp aim too low (1.8)

**MOT #4** 2014-10-03 13:10**MOT test number** 326796574254**Result** ✓ Passed

**MOT #3**

2013-10-18 12:35

**MOT test number**

299461893278

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** N/s rear tyre outer sidewall buffer torn
- Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Items removed from driver's view prior to test
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components

**MOT #2**

2012-11-06 16:11

**MOT test number**

535381312399

**Result**

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #1**

2012-11-05 14:28

**MOT test number**

756740712348

**Result**

✗ Failed

- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
17 January 2025

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	17 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	<b>RE59XEY</b>
Plate since	2019-03-28
Current registration	<b>RE59XEY</b>
Plate since	2019-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-13
Last registration	2024-01-18
Complete history	<a href="#">See info</a>



Registration #1	2009-11-13	25 mi
Registration #2	2012-11-05	48.595 mi
Registration #3	2012-11-06	48.595 mi
Registration #4	2013-10-18	55.992 mi
Registration #5	2014-10-03	64.049 mi
Registration #6	2015-10-09	71.257 mi
Registration #7	2015-10-13	71.259 mi
Registration #8	2016-10-10	75.920 mi
Registration #9	2016-10-10	75.920 mi
Registration #10	2017-10-12	80.053 mi
Registration #11	2019-05-20	95.277 mi
Registration #12	2019-05-20	95.277 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1424 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1435 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

**Engine number**

CCZ 013325