



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Black
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	40.9 mpg
Consumption combined	32.5 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-06
Pictures	9
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-05
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #23</b>	2021-06-18 10:31
<b>MOT test number</b>	550410279685
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-06-17
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Minor</b>	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #22</b>	2020-05-16 10:10
<b>MOT test number</b>	282080515425
<b>Result</b>	✓ Passed
<b>Advice</b>	Engine light on

<b>MOT #21</b>	2020-03-20 09:35
<b>MOT test number</b>	325588460449
<b>Result</b>	✗ Failed
<b>Advice</b>	Engine light on
<b>Fail</b>	Front Windscreen damaged and affecting the driver's view of an obligatory external mirror (3.2 (a) (ii))

<b>MOT #20</b>	2019-03-01 17:22
<b>MOT test number</b>	463035140365
<b>Result</b>	✓ Passed

**MOT #19** 2019-02-22 15:48**MOT test number** 508488222753**Result** ✗ Failed**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Offside Front Headlamp aim so that beam "kick up" is not visible on the screen (4.1.2 (a))**MOT #18** 2018-03-10 14:42**MOT test number** 266900723760**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #17** 2018-03-09 15:59**MOT test number** 464346055812**Result** ✗ Failed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #16** 2016-09-09 15:12**MOT test number** 604147221094**Result** ✓ Passed

**MOT #15** 2015-09-08 13:38**MOT test number** 652567436310**Result** ✓ Passed**Advice** Engine light on**MOT #14** 2014-09-26 12:33**MOT test number** 395439964457**Result** ✓ Passed**Notice** Engine light on**MOT #13** 2014-09-26 10:16**MOT test number** 535709864283**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #12** 2013-09-30 11:31**MOT test number** 116523373238**Result** ✓ Passed**MOT #11** 2013-09-30 09:15**MOT test number** 329173773275**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**Notice** Engine light on**MOT #10** 2012-09-18 14:21**MOT test number** 399752262476**Result** ✓ Passed

**MOT #9** 2012-09-18 10:22**MOT test number** 316992662253**Result** ✗ Failed**Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)**MOT #8** 2011-09-22 17:22**MOT test number** 465825961259**Result** ✓ Passed**Notice** Engine light on**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2010-09-29 16:03**MOT test number** 324592570263**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2010-09-28 18:06**MOT test number** 772811770248**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2009-09-28 12:42**MOT test number** 844911879225**Result** ✓ Passed



MOT #4 2009-09-28 11:32

MOT test number 524581879263

Result ✗ Failed

**Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)

MOT #3 2008-10-02 11:47

MOT test number 653676178212

Result ✓ Passed

**Notice** N/s/rtyre damaged and cracked

**Notice** Windscreen stonechip zone b

MOT #2 2007-10-08 17:52

MOT test number 484231787204

Result ✓ Passed

MOT #1 2006-09-21 10:10

MOT test number 170364266216

Result ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>LM51TCJ</b>
Plate since	2024-03-29
Current registration	<b>LM51TCJ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-12-06
Last registration	2021-06-18
Complete history	<a href="#">See info</a>



Registration #1	2001-12-06	9 mi
Registration #2	2006-09-21	24.854 mi
Registration #3	2007-10-08	28.558 mi
Registration #4	2008-10-02	31.371 mi
Registration #5	2009-09-28	39.405 mi
Registration #6	2009-09-28	39.405 mi
Registration #7	2010-09-28	43.649 mi
Registration #8	2010-09-29	43.649 mi
Registration #9	2011-09-22	45.098 mi
Registration #10	2012-09-18	48.927 mi
Registration #11	2012-09-18	48.927 mi
Registration #12	2013-09-30	53.099 mi
Registration #13	2013-09-30	53.099 mi
Registration #14	2014-09-30	53.099 mi
Registration #15	2014-09-30	53.099 mi
Registration #16	2014-09-30	53.099 mi
Registration #17	2014-09-30	53.099 mi
Registration #18	2014-09-30	53.099 mi
Registration #19	2014-09-30	53.099 mi
Registration #20	2014-09-30	53.099 mi
Registration #21	2014-09-30	53.099 mi
Registration #22	2014-09-30	53.099 mi
Registration #23	2014-09-30	53.099 mi
Registration #24	2014-09-30	53.099 mi
Registration #25	2014-09-30	53.099 mi
Registration #26	2014-09-30	53.099 mi

**More info** >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2

Engine number

AQY252807