





report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE 16V
Colour	Black
Year of manufacture	2007
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 4.250 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2021-09-04
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	4
Total items failed	13

MOT #16	2020-09-04 12:11
MOT test number	646995645516
Result	✓ Passed
Next expiry date	2021-09-04

MOT #15	2019-09-05 11:12
MOT test number	815361440118
Result	✓ Passed

MOT #14	2019-09-04 11:34
MOT test number	845852182524
Result	X Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #13	2018-08-29 15:55
MOT test number	901658954092
Result	✓ Passed

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT test number
929275426413

Result

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Central Rear Seat belt flexible stalk damaged (7.1.2 (b) (i))

Fail Nearside Side repeater not working (4.4.1 (a) (ii))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #11 2017-09-02 09:35 **MOT** test number 526868933008 Result ✓ Passed **MOT #10** 2017-09-02 08:13 **MOT** test number 169274243488 Result × Failed Fail Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2) Pass with rectification Offside Rear Stop lamp not working (1.2.1b) Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f) **Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b) **Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

MOT #9	2016-09-05 09:12
MOT test number	805361745988
Result	✓ Passed

CarCheck.co.uk page 3/12



Result

EA07WWU

report date: 2024-03-29

✓ Passed

MOT #8

MOT test number

Result

Pass with rectification

Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #7

MOT test number

987243025266

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification

Offside Rear Stop lamp not working (1.2.1b)

MOT #5 2014-08-15 12:43 **MOT** test number 916307624280 Result ✓ Passed 2013-07-23 16:42 **MOT #4** 387344803448 **MOT test number** Result ✓ Passed **MOT** #3 2012-04-27 10:58 **MOT** test number 415968312140

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2		2011-04-28 15:25
MOT test	number	769188311178
Result		✓ Passed
Notice	Nearside rear tyre worn	
Notice	Nearside front tyre worn on edges	

MOT #1	2010-03-29 12:03
MOT test number	340238880075
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check

Tax expired: 22 August 2021



X **MOT**

Expired: 4 September 2021

Tax status	Expired at 22 August 2021
Days left	981 days too late
MOT expiry date	4 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

EA07WWU

report date: 2024-03-29

Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

See in this check if this RENAULT had different number plates.

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2007-03-30
Last registration	2020-09-04
Complete history	See info



Registration #1	2007-03-30	27 mi
Registration #2	2010-03-29	19.273 mi
Registration #3	2011-04-28	23.944 mi
Registration #4	2012-04-27	28.503 mi
Registration #5	2013-07-23	35.705 mi
Registration #6	2014-08-15	43.066 mi
Registration #7	2015-08-11	48.410 mi
Registration #8	2016-09-05	59.052 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1940 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1135 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 12/12