



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	2007
Top speed	96 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-06-05
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-14
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	22
Total items failed	23

MOT #21 2024-02-15 11:35

MOT test number 238582784087

Result ✓ Passed

Next expiry date 2025-02-14

Advice Offside Rear Position lamp slightly affected by the operation of another lamp (4.2.3 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #20 2022-11-18 16:46

MOT test number 243980690889

Result ✓ Passed

**MOT #19**

2022-11-07 11:08

MOT test number

454968313751

Result

✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Top bush or bearing**Fail** Nearside Rear All direction indicators not working (4.4.1 (a) (ii))**Advice** Nearside Front Top bush or bearing**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #18**

2021-11-25 11:12

MOT test number

534421079382

Result

✓ Passed

Advice Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17**

2020-11-17 15:52

MOT test number

223190466692

Result

✓ Passed

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #16**

2019-05-28 11:08

MOT test number

773253556814

Result

✓ Passed

**MOT #15** 2018-11-09 16:14**MOT test number** 763121765385**Result** ✓ Passed**MOT #14** 2018-11-09 09:49**MOT test number** 245548956075**Result** ✗ Failed

- Fail** Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Central Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Advice** Non obligatory mirror damaged
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MOT #13 2017-11-10 14:41**MOT test number** 826490134337**Result** ✓ Passed

- Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #12** 2017-11-10 12:03**MOT test number** 372211144889**Result** ✗ Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)

Pass with rectification Offside Headlamp aim too high (1.8)

Fail Nearside Rear Outer Road wheel bead rim badly distorted (4.2.A.1a)

MOT #11 2016-06-06 16:37**MOT test number** 229503463136**Result** ✓ Passed**MOT #10** 2016-06-04 08:18**MOT test number** 728606839821**Result** ✗ Failed

Fail Offside Stop lamp not working (1.2.1b)

Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Nearside Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #9 2015-06-05 09:00**MOT test number** 216656655121**Result** ✓ Passed**MOT #8** 2014-08-06 15:19**MOT test number** 385888114280**Result** ✓ Passed

**MOT #7** 2014-08-06 09:17**MOT test number** 328938514201**Result** ✗ Failed**Notice** RADIATOR LEAKING**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2013-08-20 10:24**MOT test number** 126662933213**Result** ✓ Passed**MOT #5** 2013-08-20 10:24**MOT test number** 385462833491**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2012-08-07 17:10**MOT test number** 385060122223**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2012-08-07 13:55**MOT test number** 285520922209**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #2** 2011-08-23 14:00**MOT test number** 477525731289**Result** ✓ Passed**MOT #1** 2010-08-17 16:15**MOT test number** 314639720281**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-01
Last registration	2024-02-15
Complete history	See info



Registration #1	2007-09-01	7 mi
Registration #2	2010-08-17	16.752 mi
Registration #3	2011-08-23	22.358 mi
Registration #4	2012-08-07	42.876 mi
Registration #5	2012-08-07	42.876 mi
Registration #6	2013-08-20	49.756 mi
Registration #7	2014-08-06	55.787 mi
Registration #8	2014-08-06	55.787 mi
Registration #9	2015-06-05	61.666 mi
Registration #10	2016-06-04	52.791 mi
Registration #11	2016-06-06	52.791 mi
Registration #12	2016-06-06	52.791 mi
Registration #13	2016-06-06	52.791 mi
Registration #14	2016-06-06	52.791 mi
Registration #15	2016-06-06	52.791 mi
Registration #16	2016-06-06	52.791 mi
Registration #17	2016-06-06	52.791 mi
Registration #18	2016-06-06	52.791 mi
Registration #19	2016-06-06	52.791 mi
Registration #20	2016-06-06	52.791 mi
Registration #21	2016-06-06	52.791 mi
Registration #22	2016-06-06	52.791 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	2475 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	3760991