




report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | BMW |
| Model | 530 530D M SPORT |
| Colour | Black |
| Year of manufacture | 2008 |
| Top speed | 154 mph |
| 0 - 60 mph | 6.8 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 235 BHP |
| Max. torque | 500 Nm at 3.000 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 31.0 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 42.8 mpg |
| CO2 emission | 176 g/km |
| CO2 label | I |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-12 |
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 21 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #15 | 2023-05-13 13:18 |
| MOT test number | 318095140395 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-12 |

| | |
|-----------------|------------------|
| MOT #14 | 2022-02-18 12:38 |
| MOT test number | 554470402065 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #13 | 2021-02-20 14:01 |
| MOT test number | 819079739300 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #12 | 2020-02-18 11:53 |
| MOT test number | 884628366041 |
| Result | ✓ Passed |

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement
INNER ARM BUSH (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged SIDE WALL (5.2.3 (d) (ii))

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement
INNER BUSH (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged SIDE WALL (5.2.3 (d) (ii))

**MOT #11** 2019-02-21 11:28**MOT test number** 425724470959**Result** ✓ Passed

Advice Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords s/wall (5.2.3 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10 2019-02-20 11:53**MOT test number** 149182265523**Result** ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Inner Tyre has a cut but not deep enough to reach the ply or cords s/wall (5.2.3 (d) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9 2018-02-20 14:31**MOT test number** 975571226938**Result** ✓ Passed

Advice Nearside Front Outer wheel rim damaged

Advice Front brake pads - 4mm approx.

Advice Front number plate deteriorated

**MOT #8** 2018-02-20 10:41**MOT test number** 878357739300**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Outer wheel rim damaged**Advice** Front brake pads - 4mm**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Front number plate deteriorated**MOT #7** 2017-01-30 11:50**MOT test number** 228448049085**Result** ✓ Passed**MOT #6** 2016-02-03 11:46**MOT test number** 748557474320**Result** ✓ Passed**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-02-12 11:55**MOT test number** 159593045469**Result** ✓ Passed**Notice** Uneven n.s.r. tyre wear.**MOT #4** 2014-02-08 08:41**MOT test number** 236839634040**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)



| | |
|-----------------|--|
| MOT #3 | 2013-02-02 12:17 |
| MOT test number | 896883333089 |
| Result | ✓ Passed |
| MOT #2 | 2012-02-21 13:58 |
| MOT test number | 389172152008 |
| Result | ✓ Passed |
| MOT #1 | 2011-01-06 10:14 |
| MOT test number | 366006101067 |
| Result | ✓ Passed |
| Notice | O/side rear tyre on 3mm |
| Advice | Parking brake lever has little reserve travel (3.1.6b) |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
12 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 January |
| Days left | 248 |
| MOT expiry date | 12 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2008-01-09 |
| Last registration | 2023-05-13 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-01-09 | 17 mi |
| Registration #2 | 2011-01-06 | 34.940 mi |
| Registration #3 | 2012-02-21 | 48.863 mi |
| Registration #4 | 2013-02-02 | 64.092 mi |
| Registration #5 | 2014-02-08 | 79.996 mi |
| Registration #6 | 2015-02-12 | 91.490 mi |
| Registration #7 | 2016-02-03 | 108.263 mi |
| Registration #8 | 2017-01-30 | 126.975 mi |
| Registration #9 | 2018-05-29 | 151.277 mi |
| Registration #10 | 2019-05-29 | 171.277 mi |
| Registration #11 | 2020-05-29 | 191.277 mi |
| Registration #12 | 2021-05-29 | 211.277 mi |
| Registration #13 | 2022-05-29 | 231.277 mi |
| Registration #14 | 2023-05-29 | 251.277 mi |
| Registration #15 | 2024-05-29 | 271.277 mi |
| Registration #16 | 2025-05-29 | 291.277 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1846 mm |
| Height | 1469 mm |
| Length | 4841 mm |
| Wheel base | 2888 mm |
| Kerb weight | 1675 kg |
| Max. allowed weight | 2160 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

Engine number

24556777