





report date: 2024-03-29

General information

Make	NISSAN
Model	PULSAR ACENTA DIG-T
Colour	Blue
Year of manufacture	2016
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.198 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

_		•		_	-
-	n	т	rv	,	

Elitiy 1	
Date	2021-02-03
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/11



FN66HGU report date: 2024-03-29

MOT history

MOT expiry date	2024-10-29
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #6	2023-10-30 12:23
MOT test number	870617111402
Result	✓ Passed
Next expiry date	2024-10-29

MOT #5		2022-11-30 09:54
MOT test	number	263568877839
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.3mm (5.2.3 (e))	
Advice	Horn poor	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #4	2021-12-10 09:38
MOT test number	175731196831
Result	✓ Passed
Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #3	2020-12-12 13:07
MOT test number	396880653448
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2019-10-22 07:31

MOT test number 157141263354

Result
✓ Passed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Rear Integral body structure is deformed but structural rigidity is not significantly reduced

(6.1.1 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2019-10-21 16:44

MOT test number 201312913716

Result X Failed

Advice Offside Rear Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))

Fail Horn sound not in accordance with requirements (7.7 (c))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

^	
Owner	history
OWITCE	IIISCOLY

o mile mesery		
For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is		۸N
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR		

	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-09-12
Last registration	2023-10-30
Complete history	See info



Registration #1	2016-09-12	21 mi
Registration #2	2019-10-21	53.408 mi
Registration #3	2019-10-22	53.408 mi
Registration #4	2020-12-12	57.379 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		0.77

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	81%
Pedestrian	75%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1768 mm
Height	1520 mm
Length	4385 mm
Wheel base	2700 mm
Kerb weight	1304 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	46 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number 240537A