






General information

Make	CITROEN
Model	C4 GRAND PICASSO GRAND BLUEHDI FEEL S/S
Colour	Black
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В







Internet history

Entry	1

Date Pictures 2021-09-02

32

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-15
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	12
Total items failed	5

MOT #7	2023-06-13 09:58
MOT test number	181672000001
Result	✓ Passed
Next expiry date	2024-06-15
Advice Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice Front Brake disc worn, but not excessively both (1.1.14 (a) (i))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
(i)) Offside Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1 (b)
Advice Tyre slightly damaged/cracking or perishing All (5.2.3 (d) (ii))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #6		2022-06-15 14:46
MOT test	number	804991158115
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	





MOT #5	2022-06-15 11:04
MOT test number	788202309221
Result	🗙 Failed
Fail Offside Headlamp aim too low (4.1.2 (a))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

МОТ #4	2021-06-16 15:22
MOT test number	358996161806
Result	✓ Passed

МОТ #3	2021-06-01 12:50
MOT test number	786821650728
Result	🗙 Failed
Fail Nearside Front Road wheel distorted to the extent the tyre is likely to bec	ome detached (5.2.2 (c) (ii))

MOT #2	2	2021-04-22 15:59
MOT te	st number	119628766811
Result		🗙 Failed
Fail	Nearside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))	
Fail	Offside Obligatory mirror insecure (3.3 (b) (ii))	
Fail	Nearside Front Road wheel distorted to the extent the tyre is likely to become detac	hed (5.2.2 (c) (ii))

MOT #1	2020-02-14 13:51
MOT test number	522408823448
Result	✓ Passed
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	





Tax & MOT check

✓ Taxed	✓ МОТ
Tax due: 1 September 2024	Expires: 15 June 2024
Tax status	Valid until 1 September
Days left	126
MOT expiry date 15 June 2024	
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		AMPL
Date		· · ·
Category	1000000	AMPL
Туре		

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-28
Last registration	2023-06-13
Complete history	<u>See info</u>



Registration #1	2017-04-28	15 mi
Registration #2	2020-02-14	24.115 mi
Registration #3	2021-04-22	25.473 mi
Registration #4	2021-06-01	25.480 mi
Registration #5	2021-06-16	25.488 mi
Registration #6		11.117 est
Registration #7		11.177 esi
Registration #8		11.177 esi
Registration #9		10.000 est

More info >





Safety ratings		
NCAP rating	****	o de la construcción de la const
Video	<u>see crash video</u>	
Dimensions & weight		
Width		1826 mm
Height		1644 mm
Length		4597 mm
Wheel base		2840 mm
Kerb weight		1347 kg
Max. allowed weight		2175 kg
Additional information		
Fuel tank capacity		55 l
Fuel delivery		Direct Injection
		2
Number of doors		5
Number of doors Number of seats		
		5