



KH53ULY

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT T220 LWB P/V
Colour	White
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-24
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #19	2021-05-11 15:47
MOT test number	963011691727
Result	✓ Passed
Next expiry date	2022-05-10
Minor	Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #18	2019-05-15 14:20
MOT test number	188901490578
Result	✓ Passed
Advice	Steering column universal joint deformed but serviceable (2.1.3 (c) (i))
Advice	Offside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Advice	Nearside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MOT #17	2019-05-15 14:20
MOT test number	468383426475
Result	✗ Failed
Advice	Nearside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Pass with rectification	Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
Advice	Steering column universal joint deformed but serviceable (2.1.3 (c) (i))
Advice	Offside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))
Pass with rectification	Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
Pass with rectification	Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #16**

2018-05-15 08:21

MOT test number

417370469672

Result

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Rear Body has slight corrosion (6.1.B.2)
- Advice** Nearside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Offside Rear Body has slight corrosion (6.1.B.2)

MOT #15

2018-05-15 08:21

MOT test number

645148880000

Result

✗ Failed

- Advice** Nearside Rear Body has slight corrosion (6.1.B.2)
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Rear Body has slight corrosion (6.1.B.2)
- Advice** Nearside Front Upper Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #14

2017-05-09 08:26

MOT test number

161732619101

Result

✓ Passed

- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #13** 2017-05-09 08:26**MOT test number** 405030014919**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #12** 2016-05-11 11:00**MOT test number** 160865944625**Result** ✓ Passed**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #11** 2016-05-11 11:00**MOT test number** 549375288650**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #10** 2015-05-07 09:32**MOT test number** 927887725113**Result** ✓ Passed**MOT #9** 2014-05-12 14:39**MOT test number** 806162634172**Result** ✓ Passed



MOT #8	2013-01-17 12:48
MOT test number	126757113427
Result	✓ Passed
MOT #7	2012-01-18 15:47
MOT test number	647208412022
Result	✓ Passed
MOT #6	2011-01-17 15:35
MOT test number	557127811023
Result	✓ Passed
MOT #5	2010-01-12 15:46
MOT test number	171962910082
Result	✓ Passed
MOT #4	2009-01-19 14:41
MOT test number	621939619004
Result	✓ Passed
MOT #3	2009-01-19 14:41
MOT test number	961009719044
Result	✗ Failed
<div>Pass with rectification Nearside Front Headlamp aim too high (1.8)</div>	
MOT #2	2008-01-18 13:37
MOT test number	562818518079
Result	✓ Passed



MOT #1	2007-01-18 10:36
MOT test number	124828117431
Result	✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-01-19
Last registration	2021-05-11
Complete history	See info



Registration #1	2004-01-19	26 mi
Registration #2	2007-01-18	37.671 mi
Registration #3	2008-01-18	52.733 mi
Registration #4	2009-01-19	67.686 mi
Registration #5	2010-01-12	82.602 mi
Registration #6	2011-01-17	97.947 mi
Registration #7	2012-01-18	113.780 mi
Registration #8	2013-01-17	129.047 mi
Registration #9	2014-05-12	142.770 mi
Registration #10	2015-05-07	152.411 mi
Registration #11	2016-05-07	162.052 mi
Registration #12	2017-05-07	171.693 mi
Registration #13	2018-05-07	181.334 mi
Registration #14	2019-05-07	190.975 mi
Registration #15	2020-05-07	200.616 mi
Registration #16	2021-05-11	210.257 mi
Registration #17	2022-05-11	219.898 mi
Registration #18	2023-05-11	229.539 mi
Registration #19	2024-03-29	239.180 mi
Registration #20	2025-03-29	248.821 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1795 mm
Kerb weight	1435 kg
Max. allowed weight	2260 kg

Additional information

Number of seats	2
Number of axles	2
Engine number	4K76189